## Jamshedpur NAC

## SITE VISIT REPORT

| Proposal Details |                                     |                  |                              |  |  |  |  |
|------------------|-------------------------------------|------------------|------------------------------|--|--|--|--|
| Owner Name       | : M/S L.I.C OF INDIA REPRESENTED BY | Site Visit Date  | : 19 December, 2023          |  |  |  |  |
| Applicant Name   | : ANDOP KUMAT                       | File No.         | : JNAC/BP/0098/W2/2023       |  |  |  |  |
| Ward No.         | : W2                                | Case Type        | : Addition Alteration        |  |  |  |  |
| Thana No.        | : 1158                              | Plot No.         | H.NO :- NIL, KADMA FARM AREA |  |  |  |  |
| Road No. / Name  | : LIC ZONAL TRAINING CENTRE, KADMA  | Registration No. | : JNAC/ENG/0005/2016         |  |  |  |  |

| Site Visit Checklist |   |                            |           |        |  |
|----------------------|---|----------------------------|-----------|--------|--|
| #                    | Description   | As On Site                 | Objection | Remark |  |
| 1.                   | Whether Existing at Site  | Yes                        |           |        |  |
| 2.                   | Whether connected with an existing public road  | Yes                        |           |        |  |
| 3.                   | Status of road  | Public                     |           |        |  |
| 4.                   | Nature of Road  | Blacktop                   |           |        |  |
| 5.                   | Width of approach road  | 12                         |           |        |  |
| 6.                   | Whether road side drain exists  | Yes                        |           |        |  |
| 7.                   | if Whether road side drain exists is Yes - Width  | 300 MM                     |           |        |  |
| 8.                   | if Whether road side drain exists is Yes - Nature   | Concrete                   |           |        |  |
| 9.                   | if Whether road side drain exists is Yes - Whether connected to   | Public Drain               |           |        |  |
| 10.                  | Whether the site is at road junction  | No                         |           |        |  |
| 11.                  | Level of site in relation to approach road  | +0.15                      |           |        |  |
| 12.                  | Whether the area is subject to  | NA                         |           |        |  |
| 13.                  | Whether the locality is   | Developing                 |           |        |  |
| 14.                  | Distance of the plot from the nearest temple/<br>monument / Airport/ Other important building   | LIC OFFICE<br>BUILDING     |           |        |  |
| 15.                  | The vertical and horizontal distance from 33 KV/11 KV electric line   | 12/2 KM                    |           |        |  |
| 16.                  | Whether the Site is vacant  | No                         |           |        |  |
| 17.                  | if Whether the Site is vacant No - Stage of construction  | 1                          |           |        |  |
| 18.                  | if Whether the Site is vacant No - No of Storey   | 1                          |           |        |  |
| 19.                  | if Whether the Site is vacant No - Nature of construction   | RCC                        |           |        |  |
| 20.                  | if Whether the Site is vacant No - Sketch enclosed at page  | No                         |           |        |  |
| 21.                  | Plot size (As per measurement)(In Sqmt)   | 27696.68                   |           |        |  |
| 22.                  | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel   | No                         |           |        |  |
| 23.                  | Sketch site plan showing the location of the site,<br>important land marks and connectivity with the main<br>road is enclosed. (For site not located on main road) at<br>page | Yes                        |           |        |  |
| 24.                  | Any other information.  | No                         |           |        |  |
| 25.                  | Verified the Amins report with/without site inspection and found correct  | No                         |           |        |  |
| 26.                  | If No, Reason   | Tata company lease<br>area |           |        |  |
| 27.                  | Land Use  | Residential                |           |        |  |
| 28.                  | Road  | Yes                        |           |        |  |
| 29.                  | Sewerage  | Yes                        |           |        |  |
| 30.                  | Drainage  | Yes                        |           |        |  |

| 31. | Water facility   | Yes            |
|-----|--|----------------|
| 32. | Availability of drain                                  | Yes            |
| 33. | Telephone  | No             |
| 34. | Electricity  | Yes            |
| 35. | Dealing with inflammable/chemical                      | No             |
| 36. | Occupancy  | No             |
| 37. | EAST   | Other building |
| 38. | WEST   | Other building |
| 39. | NORTH  | Road           |
| 40. | SOUTH  | Other building |
| 41. | Length of the Road(In Mtr.)                            | Up to 50 meter |
| 42. | Existing Width of the Road(In Mtr.)                    | 12             |
| 43. | Proposed Width of the Road as per Master Plan(In Mtr.) | 12             |
| 44. | Width of the RoadWidening(In Mtr.)                     | 0              |
| 45. | Plot area (As per deed)                                | 0              |

## Site Visit Photographs :









जमशेदपुर, झारखंड, भारत R568+686, जलियान, केसर कॉलोनी, कदमा, जमशेदपुर, झारखंड 831005, भारत Lat 22.811143° Long 86.165714° 14/12/23 01:53 PM GMT +05:30





Recommendation : Verified & found Ok

**Remark** : Additional one Floor site inspection done . verified and found ok. An Existing Ground floor building is present at site, and minimum set beck found ok check list submitted. Hence it can be recommended for sanction.

Pranaw Kumar Thakur Junior Engg