Adityapur Municipal Corporation

SITE VISIT REPORT

Proposal Details

Owner Name : SHANKAR KUMAR Site Visit Date : 14 June, 2017

Applicant Name : MUKESH KUMAR File No. : AMC/BP/0010/W04/2017

Ward No. : W04 Case Type : New Thana No. : 66 Plot No. 8/1618

Road No. / Name : Satbahini/Gamharia/Tata kandra Registration No. : AMC/ENG/0004/2017

Site Visit Checklist							
#	Description	As On Site	Objection	Remark			
1.	Approach Road						
2.	Whether Existing at Site	Yes					
3.	Whether connected with an existing public road	Yes					
4.	Status of road	Public					
5.	Nature of Road	Blacktop					
6.	Width of approach road	120 feet					
7.	Whether road side drain exists	Yes					
8.	if Whether road side drain exists is Yes - Width	4 feet					
9.	if Whether road side drain exists is Yes - Nature	Concrete					
10.	if Whether road side drain exists is Yes - Whether connected to	Public Drain					
11.	if Whether road side drain exists is No - Distance from nearest drain	1 feet					
12.	if Whether road side drain exists is No - easibility to connect	Yes					
13.	if Whether road side drain exists is No - Scope of widening of road	1 feet					
14.	Site Situation						
15.	Whether the site is at road junction	Yes					
16.	Level of site in relation to approach road	yes					
17.	Whether the area is subject to	Low lying land					
18.	Whether the locality is	Developed					
19.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	200 feet					
20.	The vertical and horizontal distance from 33 KV/11 KV electric line	15 feet					
21.	Site Details						
22.	Whether the Site is vacant	No		After Demolession hurts shops and old building plot will be vacant			
23.	if Whether the Site is vacant No - Stage of construction	1					
24.	if Whether the Site is vacant No - No of Storey	1					
25.	if Whether the Site is vacant No - Nature of construction	RCC					
26.	if Whether the Site is vacant No - Sketch enclosed at page	Yes					
27.	Plot size (As per measurement)(In Sqmt)	683.08					
28.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No					

Page 1 of 2 Printed on: 14 July, 2017

29.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	yes	
30.	Any other information.	no	
31.	Verification Details		
32.	Verified the Amins report with/without site inspection and found correct	No	
33.	If No, Reason	no	
34.	Verified the cadastral map		
35.	Land Use	Residential	
36.	Existing off site Physical Infrastructure:		
37.	Road	Yes	
38.	Sewerage	No	
39.	Drainage	Yes	
40.	Water facility	Yes	
41.	Availability of drain	Yes	
42.	Telephone	Yes	
43.	Electricity	Yes	
44.	Risk Parameter		
45.	Dealing with inflammable/chemical	No	
46.	Occupancy	No	
47.	Site Surrounded by (physical features)		
48.	EAST	Attached	
49.	WEST	Attached	
50.	NORTH	Attached	
51.	SOUTH	Attached	
52.	Length of the Road(In Mtr.)	Exceeding 600 meter and upto 1000 meter	
53.	Existing Width of the Road(In Mtr.)	120	
54.	Proposed Width of the Road as per Master Plan(In Mtr.)	120	
55.	Width of the RoadWidening(In Mtr.)	120	

David Oreya Junior Engg

Page 2 of 2 Printed on: 14 July, 2017