

Adityapur Municipal Corporation

SITE VISIT REPORT

Proposal Details

| | |
|---|--------------------------------------|
| Owner Name : MR. BRIJESH KUMAR | Site Visit Date : 25 August, 2020 |
| Applicant Name : Anoop Kumar | File No. : AMC/BP/0071/W06/2019 |
| Ward No. : W06 | Case Type : New |
| Thana No. : 02/66 | Plot No. : 2493 |
| Road No. / Name : MAHABIR NAGAR BARA GAMHARIA NEAR RAILWAY STATION GAMHARIA | Registration No. : AMC/ENG/0024/2016 |

Site Visit Checklist

| # | Description | As On Site | Objection | Remark |
|-----|--|---------------------------------------|-----------|--------|
| 1. | Whether Existing at Site | Yes | | |
| 2. | Whether connected with an existing public road | Yes | | |
| 3. | Status of road | Public | | |
| 4. | Nature of Road | Kutchha | | |
| 5. | Width of approach road | 3.66 mtr | | |
| 6. | Whether road side drain exists | No | | |
| 7. | if Whether road side drain exists is No - Distance from nearest drain | 10 mtr | | |
| 8. | if Whether road side drain exists is No - easibility to connect | Yes | | |
| 9. | if Whether road side drain exists is No - Scope of widening of road | 0.001 | | |
| 10. | Whether the site is at road junction | Yes | | |
| 11. | Level of site in relation to approach road | -0.01 mtr | | |
| 12. | Whether the area is subject to | Water logging | | |
| 13. | Whether the locality is | Un-developed | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | 250 mtr from Gamharia railway station | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | 11KV/60 mtr | | |
| 16. | Whether the Site is vacant | Yes | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 99.14 | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | Gamharia railway station | | |
| 20. | Any other information. | N/A | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | |
| 22. | Land Use | Residential | | |
| 23. | Road | Yes | | |
| 24. | Sewerage | No | | |
| 25. | Drainage | No | | |
| 26. | Water facility | No | | |
| 27. | Availability of drain | Yes | | |
| 28. | Telephone | No | | |
| 29. | Electricity | Yes | | |

| | | | | |
|-----|--|----------------------|--|--|
| 30. | Dealing with inflammable/chemical | No | | |
| 31. | Occupancy | Yes | | |
| 32. | EAST | PLOT NO- 3056 | | |
| 33. | WEST | 3.66 MTR WIDE ROAD | | |
| 34. | NORTH | PLOT NO- 3058 & 3049 | | |
| 35. | SOUTH | 3.66 MTR WIDE ROAD | | |
| 36. | Length of the Road(In Mtr.) | Up to 50 meter | | |
| 37. | Existing Width of the Road(In Mtr.) | 3.66 | | |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 3.66 | | |
| 39. | Width of the RoadWidening(In Mtr.) | 0.001 | | |
| 40. | Plot area (As per deed) | 99.14 | | |

Site Visit Photographs :





Recommendation : Verified & found Ok

Remark : ok

Binod Kumar
Assistant Engineer