Adityapur Municipal Corporation

SITE VISIT REPORT

Proposal Details

Owner Name : SUMAN KUMAR JHA Site Visit Date : 27 June, 2020

Applicant Name : Abhishek Tewari File No. : AMC/BP/0010/W15/2020

Ward No. : W15 Case Type : New Thana No. : 131 Plot No. 1113(P)

Road No. / Name : Registration No. : AMC/ARC/0026/2016

| Site Visit Checklist | | | | | |
|----------------------|--|-------------------------------|-----------|--------|--|
| # | Description | As On Site | Objection | Remark | |
| 1. | Whether Existing at Site | Yes | | | |
| 2. | Whether connected with an existing public road | Yes | | | |
| 3. | Status of road | Public | | | |
| 4. | Nature of Road | Kutchha | | | |
| 5. | Width of approach road | 7.62 mtr | | | |
| 6. | Whether road side drain exists | No | | | |
| 7. | if Whether road side drain exists is No - Distance from nearest drain | 10 mtr | | | |
| 8. | if Whether road side drain exists is No - easibility to connect | Yes | | | |
| 9. | if Whether road side drain exists is No - Scope of widening of road | 0.001 | | | |
| 10. | Whether the site is at road junction | No | | | |
| 11. | Level of site in relation to approach road | +0.01 mtr | | | |
| 12. | Whether the area is subject to | Low lying land | | | |
| 13. | Whether the locality is | Un-developed | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | 200 mtr from NIT Adityapur | | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | 11KV/60 mtr | | | |
| 16. | Whether the Site is vacant | Yes | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 216.17 | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | NIT Adityapur | | | |
| 20. | Any other information. | N/A | | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | | |
| 22. | Land Use | Residential | | | |
| 23. | Road | Yes | | | |
| 24. | Sewerage | No | | | |
| 25. | Drainage | No | | | |
| 26. | Water facility | No | | | |
| 27. | Availability of drain | Yes | | | |
| 28. | Telephone | No | | | |
| 29. | Electricity | Yes | | | |
| 30. | Dealing with inflammable/chemical | No | | | |
| | | • | | | |

Page 1 of 3 Printed on: 29 July, 2020

| 31. | Occupancy | Yes | |
|-----|--|---------------------------------------|--|
| 32. | EAST | SUB PLOT 90 | |
| 33. | WEST | 7.62 ROAD | |
| 34. | NORTH | SUB PLOT 94 | |
| 35. | SOUTH | SUB PLOT 96 | |
| 36. | Length of the Road(In Mtr.) | Exceeding 50 meter and upto 100 meter | |
| 37. | Existing Width of the Road(In Mtr.) | 7.62 | |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 7.62 | |
| 39. | Width of the RoadWidening(In Mtr.) | 0.001 | |
| 40. | Plot area (As per deed) | 222.65 | |

Site Visit Photographs:







Page 2 of 3 Printed on: 29 July, 2020





Recommendation :

Remark :

Binod Kumar Assistant Engineer

Page 3 of 3 Printed on: 29 July, 2020