

Form IV

CSS No: DX/NKS/CSS/007/2022
Issue Date of CSS : 15/06/2022

Certificate for Structure Stability (CSS)

(This certificate Adheres to Jharkhand Municipal Act 2011, Jharkhand Regional Development Authority Act 2002, Mineral Area Development Authority Act, Jharkhand Industrial Area Development Authority Act, & Jharkhand Building Bye Laws 2016)

Owner / Builder Name	: Ravi Prasad Sumita Prasad	Village Name / Mouza Name	: Asangri
Name of Local body	: AMC	Project / Proposal Type	: Residential Building
Plot No.	: 1422/1093	Occupancy Type/Purpose	: Residential
Ward No.	: 22(CN)	Supervision Certificate (SC) (No)	: DX/NKS/8C/007/2022
Thana name / No.	: NIT/131	Issue date of Supervision Certificate	: 15/06/2022
Street address	: Asangri	Application / file no.	: AMC/TEMP/BP/0052/2022/2022
Landmark / Locality	: Sai Prangan	Date and Time of Application / file	: 15/06/2022
Khastra/ Khaitan No.	: 8/187	Name of Associated Technical Person (if any)	: Nilnil Shukla.

With respect to the building work for above said project/proposal type with respect of above referred plot, I certify that the structural calculations, plans and details including the relevant specifications of the building prepared by me, satisfy the structural safety requirements for all situations including natural disasters like cyclone & earth quake etc: as applicable under the Byelaws and stipulated under Part-6 (Structural Design) of the National Building Code of India, 2005 and other relevant codes; and the information given in this is factually correct to the best of my knowledge.

I undertake the responsibility with regard to supervision of the work at each and every stage of construction of the structure, regularly to the effect that the building is being constructed conforming to the structural plan prepared structural calculations, plans and details including the relevant specifications of the building prepared by me.

I will be responsible and liable for action by (Name of ULB) Govt of Jharkhand if the plan/ design contain misrepresentation or fraudulent information and the construction is made in deviation from structural calculations, plans and details including the relevant specifications of the building prepared by me or if there is any structural failure due wrong /unsafe structural design/ use of low quality material and/ or poor workmanship endangering the safety of inmates or public and the structural stability of the building.

Authorized Signatory

(Name of Structure Engineer / Civil Engineer)

Registration No.....

Validity No.....

Address:.....

NIKHIL KR. SHUKLA
AMC/AR/C/0045/2017

Nilnil

125, Chandrajyoti Colony
Old Furdia Road, Mangal

Authorized Signatory

(Name of Owner/Builder)

Registration No.....

Validity No.....

Address:.....

Ravi Prasad

10, Kaiser, Bangaloo, Garwa Road
Sonari