

Adityapur Municipal Corporation

SITE VISIT REPORT

| Proposal Details | | | |
|------------------|---|------------------|------------------------|
| Owner Name | : TECHNOCULTURE BUILDING CENTRE PRIVATE LIMITED | Site Visit Date | : 07 May, 2024 |
| Applicant Name | : MOHAMMAD BELAL NASIR | File No. | : AMC/BP/0020/W22/2024 |
| Ward No. | : W22 | Case Type | : New |
| Thana No. | : 131 | Plot No. | : 456 |
| Road No. / Name | : ASANGI | Registration No. | : AMC/ENG/0015/2017 |

Site Visit Checklist

| # | Description | As On Site | Objection | Remark |
|-----|--|----------------------|-----------|--------|
| 1. | Whether Existing at Site | Yes | | |
| 2. | Whether connected with an existing public road | Yes | | |
| 3. | Status of road | Public | | |
| 4. | Nature of Road | Kutchha | | |
| 5. | Width of approach road | 9.14M | | |
| 6. | Whether road side drain exists | No | | |
| 7. | if Whether road side drain exists is No - Distance from nearest drain | 30M | | |
| 8. | if Whether road side drain exists is No - easibility to connect | Yes | | |
| 9. | if Whether road side drain exists is No - Scope of widening of road | 0.03M | | |
| 10. | Whether the site is at road junction | No | | |
| 11. | Level of site in relation to approach road | +0.01M | | |
| 12. | Whether the area is subject to | NA | | |
| 13. | Whether the locality is | Developing | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | 200M FROM NIT CAMPUS | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | 50M ,11KV | | |
| 16. | Whether the Site is vacant | Yes | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 146.95 | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | Yes | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | YES | | |
| 20. | Any other information. | NA | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | |
| 22. | Land Use | Residential | | |
| 23. | Road | Yes | | |
| 24. | Sewerage | No | | |
| 25. | Drainage | No | | |
| 26. | Water facility | Yes | | |
| 27. | Availability of drain | No | | |
| 28. | Telephone | Yes | | |
| 29. | Electricity | Yes | | |
| 30. | Dealing with inflammable/chemical | No | | |

| | | | | |
|-----|--|--|--|--|
| 31. | Occupancy | Yes | | |
| 32. | EAST | 2481(p) | | |
| 33. | WEST | 2497(p) | | |
| 34. | NORTH | 9.14M | | |
| 35. | SOUTH | 2492(p) | | |
| 36. | Length of the Road(In Mtr.) | Exceeding 100 meter and upto 250 meter | | |
| 37. | Existing Width of the Road(In Mtr.) | 9.14 | | |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 9.14 | | |
| 39. | Width of the RoadWidening(In Mtr.) | 0.01 | | |
| 40. | Plot area (As per deed) | 146.95 | | |

Site Visit Photographs :





Recommendation : Verified & found Ok

Remark : Site is verified and found ok , Drawing may be approved ,May proceed for further verification

Surendra Mahto
Assistant Engineer