

1. That the building has been constructed according to the structural design and specification prepared by me, which incorporates the provisions of structural safety norms as specified in part 6 (Structural Design) of the national building code of India, 2005 and other relevant codes and the design complies with the Earthquake safety requirement.
2. That the construction has been done under my supervision and guidance and adheres to the structural drawings and specifications prepared by me and records of supervision have been maintained.

Any subsequent changes or deviation from the structural drawings and specifications shall be the responsibility of the owner / builder.

Name and signature of competent

Technical Person **RAGUNATH MAHATO**

Registration no. **CMC/DFTMN/0033/2017**

Date: **13/02/2019**

Address: **AT - TOLA-TANDUHAR (JOLHADIH) P.O - PUPUNICE, CHAS, BOKARO**

Ragunath Mahato
Ragunath Mahato
DIMICivil
Reg. No.- CMC/DFTMN/0033/2017
Chas Municipal Corporation
Chas, Bokaro

Name and Signature of Owner/Builder/Applicant **SMT-REKHA KUMARI**

Registration no.

Date: **13/02/2019**

Address: **AT - RAM NAGAR COLONY, CHAS, BOKARO**

Rekha
Rekha