Chas Municipal Corporation

SITE VISIT REPORT

Proposal Details

Owner Name : VEENA SINHA & ANITA SINHA Site Visit Date : 22 October, 2019

Applicant Name : Nirmal Kumar Sharma File No. : CMC/BP/0245/W02/2019/ALT1

Ward No.: W02Case Type: Addition AlterationThana No.: 30Plot No.121,122,124,126Road No. / Name: CMC/ARC/0001/2017

Site Visit Checklist					
#	Description	As On Site	Objection	Remark	
1.	Whether Existing at Site	Yes			
2.	Whether connected with an existing public road	Yes			
3.	Status of road	Public			
4.	Nature of Road	Kutchha			
5.	Width of approach road	12			
6.	Whether road side drain exists	Yes			
7.	if Whether road side drain exists is Yes - Width	0.45			
8.	if Whether road side drain exists is Yes - Nature	Earth			
9.	if Whether road side drain exists is Yes - Whether connected to	Public Drain			
١٥.	Whether the site is at road junction	Yes			
11.	Level of site in relation to approach road	0.01			
12.	Whether the area is subject to	Affected by drainage channel			
13.	Whether the locality is	Developing			
14.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	NO			
15.	The vertical and horizontal distance from 33 KV/11 KV electric line	NO			
16.	Whether the Site is vacant	No			
17.	if Whether the Site is vacant No - Stage of construction	4			
18.	if Whether the Site is vacant No - No of Storey	4			
19.	if Whether the Site is vacant No - Nature of construction	RCC			
20.	if Whether the Site is vacant No - Sketch enclosed at page	No			
21.	Plot size (As per measurement)(In Sqmt)	725.99			
22.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No			
23.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	YES			
24.	Any other information.	NO			
25.	Verified the Amins report with/without site inspection and found correct	Yes			
26.	Land Use	Residential			
27.	Road	Yes			
28.	Sewerage	No			
29.	Drainage	No			
30.	Water facility	No			

Page 1 of 3 Printed on : 16 January, 2020

31.	Availability of drain	No
32.	Telephone	Yes
33.	Electricity	Yes
34.	Dealing with inflammable/chemical	No
35.	Occupancy	No
36.	EAST	SURVEY NO-121
37.	WEST	ROAD WIDTH-12
38.	NORTH	SURVEY NO-121,122
39.	SOUTH	ROAD WIDTH-9.14
40.	Length of the Road(In Mtr.)	Up to 50 meter
41.	Existing Width of the Road(In Mtr.)	12
42.	Proposed Width of the Road as per Master Plan(In Mtr.)	12
43.	Width of the RoadWidening(In Mtr.)	0
44.	Plot area (As per deed)	725.99

Site Visit Photographs:





Page 2 of 3 Printed on: 16 January, 2020





Recommendation : Remark :

Roshni Priya Raj Junior Engg

Page 3 of 3 Printed on: 16 January, 2020