Chas Municipal Corporation

SITE VISIT REPORT

Proposal Details

Owner Name : BALBIR SINGH Site Visit Date : 14 July, 2020

Applicant Name : Trilochan Kumar Trivedi File No. : CMC/BP/0070/W32/2020

Ward No.: W32Case Type: NewThana No.: 30Plot No.7562

Road No. / Name : KRISHNAPURI COLONY CHAS BOKARO Registration No. : CMC/SUP/0003/2017

| Site Visit Checklist | | | | |
|----------------------|--|------------------------------|-----------|--------|
| # | Description | As On Site | Objection | Remark |
| 1. | Whether Existing at Site | Yes | | |
| 2. | Whether connected with an existing public road | Yes | | |
| 3. | Status of road | Public | | |
| 4. | Nature of Road | Concrete | | |
| 5. | Width of approach road | 4.88 | | |
| 6. | Whether road side drain exists | Yes | | |
| 7. | if Whether road side drain exists is Yes - Width | 0.45 | | |
| 8. | if Whether road side drain exists is Yes - Nature | Concrete | | |
| 9. | if Whether road side drain exists is Yes - Whether connected to | Public Drain | | |
| 10. | Whether the site is at road junction | No | | |
| 11. | Level of site in relation to approach road | 0.01 | | |
| 12. | Whether the area is subject to | Affected by drainage channel | | |
| 13. | Whether the locality is | Developing | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | 1km from nearest temple | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | NO | | |
| 16. | Whether the Site is vacant | Yes | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 141.82 | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | YES | | |
| 20. | Any other information. | NO | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | |
| 22. | Land Use | Residential | | |
| 23. | Road | Yes | | |
| 24. | Sewerage | No | | |
| 25. | Drainage | No | | |
| 26. | Water facility | No | | |
| 27. | Availability of drain | Yes | | |
| 28. | Telephone | No | | |
| 29. | Electricity | Yes | | |
| 30. | Dealing with inflammable/chemical | No | | |

Page 1 of 3 Printed on : 10 July, 2020

| 31. | Occupancy | No |
|-----|--|------------------------|
| 32. | EAST | JALESHWAR PANDIT |
| 33. | WEST | CTS NO PLOT NO 7562 |
| 34. | NORTH | 4.88 MTR WIDE ROAD |
| 35. | SOUTH | CTS NO PLOT NO 7562 |
| 36. | Length of the Road(In Mtr.) | Up to 50 meter |
| 37. | Existing Width of the Road(In Mtr.) | 4.88 |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 0 |
| 39. | Width of the RoadWidening(In Mtr.) | 0 |
| 40. | Plot area (As per deed) | 141.82 |

Site Visit Photographs:







Page 2 of 3 Printed on: 10 July, 2020



Recommendation: Verified & found Ok

Remark : ok

Deepak Kumar Junior Engg

Page 3 of 3 Printed on: 10 July, 2020