- 1. That the building has been constructed according to the structural design and specification prepared by me, which incorporates the provisions of structural safety norms as specified in part 6 (Structural Design) of the national building code of India, 2005 and other relevant codes and the design complies with the Earthquake safety requirement.
- That the construction has been done under my supervision and guidance and adheres to the structural drawings and specifications prepared by me and records of supervision have been maintained.

Any subsequent changes or deviation from the structural drawings and specifications shall be the responsibility of the owner / builder.

Name and signature of competent

Technical Person ENG Registration no. CMC/ENG/0004/2017 Date: 13/11/2020

Address: RISHAL KATRA, BYE PASS ROAD CHAS

LIDER AND

M. Kumar CMC/ENG/0004/2017

Name and Signature of Owner/Builder/Applicant SAVITRI MISTRI

Registration no. N/M

Date: 13/11/2020

Address: ASHOK VATIKA COLONY, NEAR KALI MANDIR, DARRU NAGAR CHAS

-152-

FORM-III

CERTIFICATE OF EXECUTION OF WORK AS PER STRUCTURAL SAFETY REQUIREMENTS

From	SAVITRI MISTRI W/O LT. BHOLA MISTRY
	ASHOK VATIKA COLONY,
	NEAR KALI MANDIR,
	DARKU NAGAR, CHAS
	(Name and address of the applicant in block letters)
То	
	AMC
	CHAS MUNICIPAL.
	CORPORATION

I certify;