Chas Municipal Corporation

SITE VISIT REPORT

| Proposal Details | | | | | |
|------------------|---------------|------------------|------------------------|--|--|
| Owner Name | : SHANTI DEVI | Site Visit Date | : 09 July, 2021 | | |
| Applicant Name | : RAVI KUMAR | File No. | : CMC/BP/0130/W23/2021 | | |
| Ward No. | : W23 | Case Type | : New | | |
| Thana No. | : 30 | Plot No. | 6927,6930 | | |
| Road No. / Name | : | Registration No. | : CMC/DFTMN/0024/2017 | | |
| | | | | | |

| | Site Visit Checklist | | | | |
|-----|---|--------------|-----------|--------|--|
| # | Description | As On Site | Objection | Remark | |
| 1. | Whether Existing at Site | Yes | | | |
| 2. | Whether connected with an existing public road | Yes | | | |
| 3. | Status of road | Public | | | |
| 4. | Nature of Road | Concrete | | | |
| 5. | Width of approach road | 4.57 | | | |
| 6. | Whether road side drain exists | Yes | | | |
| 7. | if Whether road side drain exists is Yes - Width | 0.45 | | | |
| 8. | if Whether road side drain exists is Yes - Nature | Concrete | | | |
| 9. | if Whether road side drain exists is Yes - Whether connected to | Public Drain | | | |
| 10. | Whether the site is at road junction | No | | | |
| 11. | Level of site in relation to approach road | 0.01 | | | |
| 12. | Whether the area is subject to | NA | | | |
| 13. | Whether the locality is | Developing | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | NO | | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | NO | | | |
| 16. | Whether the Site is vacant | Yes | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 222.65 | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | YES | | | |
| 20. | Any other information. | NO | | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | | |
| 22. | Land Use | Residential | | | |
| 23. | Road | Yes | | | |
| 24. | Sewerage | No | | | |
| 25. | Drainage | No | | | |
| 26. | Water facility | No | | | |
| 27. | Availability of drain | No | | | |
| 28. | Telephone | Yes | | | |
| 29. | Electricity | Yes | | | |
| 30. | Dealing with inflammable/chemical | No | | | |
| 31. | Occupancy | No | | | |

| 32. | EAST | PLO NO UMRAVATI DEVI |
|-----|--|-------------------------|
| 33. | WEST | ROAD 4.57 M ROAD |
| 34. | NORTH | PLOT NO USH JAISWAL |
| 35. | SOUTH | PLOT NO BIJAY SINGH |
| 36. | Length of the Road(In Mtr.) | Up to 50 meter |
| 37. | Existing Width of the Road(In Mtr.) | 4.57 |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 4.57 |
| 39. | Width of the RoadWidening(In Mtr.) | 0 |
| 40. | Plot area (As per deed) | 222.65 |

Site Visit Photographs :









Recommendation : Verified & found Ok Remark : OK

> Deepak Kumar Junior Engg