Chas Municipal Corporation

SITE VISIT REPORT

| Proposal Details | | | | | | |
|------------------|---------------------------|------------------|------------------------|--|--|--|
| Owner Name | : NITU DEVI | Site Visit Date | : 04 December, 2021 | | | |
| Applicant Name | : Trilochan Kumar Trivedi | File No. | : CMC/BP/0144/W30/2021 | | | |
| Ward No. | : W30 | Case Type | : New | | | |
| Thana No. | : 35 | Plot No. | 1009,1013 | | | |
| Road No. / Name | : | Registration No. | : CMC/SUP/0003/2017 | | | |
| | | - | | | | |

| Site Visit Checklist | | | | | | |
|----------------------|---|--|-----------|--------|--|--|
| # | Description | As On Site | Objection | Remark | | |
| 1. | Whether Existing at Site | Yes | | | | |
| 2. | Whether connected with an existing public road | Yes | | | | |
| 3. | Status of road | Public | | | | |
| 4. | Nature of Road | Kutchha | | | | |
| 5. | Width of approach road | 4.57 | | | | |
| 6. | Whether road side drain exists | No | | | | |
| 7. | if Whether road side drain exists is No - Distance from nearest drain | 1000 m | | | | |
| 8. | if Whether road side drain exists is No - easibility to connect | No | | | | |
| 9. | if Whether road side drain exists is No - Scope of widening of road | no | | | | |
| 10. | Whether the site is at road junction | No | | | | |
| 11. | Level of site in relation to approach road | 0.01 | | | | |
| 12. | Whether the area is subject to | NA | | | | |
| 13. | Whether the locality is | Developing | | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | NO | | | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | HIGH TENSION WIRE IS NOT AT SITE | | | | |
| 16. | Whether the Site is vacant | Yes | | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 202.41 | | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | YES | | | | |
| 20. | Any other information. | NO | | | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | | | |
| 22. | Land Use | Residential | | | | |
| 23. | Road | Yes | | | | |
| 24. | Sewerage | No | | | | |
| 25. | Drainage | No | | | | |
| 26. | Water facility | No | | | | |
| 27. | Availability of drain | No | | | | |
| 28. | Telephone | Yes | | | | |
| 29. | Electricity | Yes | | | | |

| 30. | Dealing with inflammable/chemical | No | |
|-----|--|----------------------------------|--|
| 31. | Occupancy | No | |
| 32. | EAST | ROAD WIDTH-4.57 M ROAD | |
| 33. | WEST | PLOT NO-GITA DEVI | |
| 34. | NORTH | PLOT NO-1014 | |
| 35. | SOUTH | PLOT NO-SITA RAM AGARWAL LAND | |
| 36. | Length of the Road(In Mtr.) | Up to 50 meter | |
| 37. | Existing Width of the Road(In Mtr.) | 4.57 | |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 0 | |
| 39. | Width of the RoadWidening(In Mtr.) | 0 | |
| 40. | Plot area (As per deed) | 202.41 | |

Site Visit Photographs :











Recommendation : Verified & found Ok Remark : ok

> Pawan Pandey Junior Engg