## **Chas Municipal Corporation**

## SITE VISIT REPORT

| Proposal Details |                        |                  |                        |  |  |
|------------------|------------------------|------------------|------------------------|--|--|
| Owner Name       | : Rina Mahato          | Site Visit Date  | : 05 January, 2023     |  |  |
| Applicant Name   | : Rupendra Kumar Singh | File No.         | : CMC/BP/0319/W29/2022 |  |  |
| Ward No.         | : W29                  | Case Type        | : New                  |  |  |
| Thana No.        | : 34                   | Plot No.         | 1457                   |  |  |
| Road No. / Name  | : Telidih              | Registration No. | : CMC/ENG/0002/2022    |  |  |

| Site Visit Checklist |   |  |           |        |  |  |
|----------------------|---|--|-----------|--------|--|--|
| #                    | Description   | As On Site                             | Objection | Remark |  |  |
| 1.                   | Whether Existing at Site  | Yes                                    |           |        |  |  |
| 2.                   | Whether connected with an existing public road  | Yes                                    |           |        |  |  |
| 3.                   | Status of road  | Public                                 |           |        |  |  |
| 4.                   | Nature of Road  | Kutchha                                |           |        |  |  |
| 5.                   | Width of approach road  | 3.66 m                                 |           |        |  |  |
| 6.                   | Whether road side drain exists  | No                                     |           |        |  |  |
| 7.                   | if Whether road side drain exists is No - Distance from nearest drain   | 45 m                                   |           |        |  |  |
| 8.                   | if Whether road side drain exists is No - easibility to connect   | Yes                                    |           |        |  |  |
| 9.                   | if Whether road side drain exists is No - Scope of widening of road   | NO                                     |           |        |  |  |
| 10.                  | Whether the site is at road junction  | No                                     |           |        |  |  |
| 11.                  | Level of site in relation to approach road  | 0.01                                   |           |        |  |  |
| 12.                  | Whether the area is subject to  | NA                                     |           |        |  |  |
| 13.                  | Whether the locality is   | Developing                             |           |        |  |  |
| 14.                  | Distance of the plot from the nearest temple/<br>monument / Airport/ Other important building   | NO                                     |           |        |  |  |
| 15.                  | The vertical and horizontal distance from 33 KV/11 KV electric line   | HIGH TENSION<br>WIRE IS NOT AT<br>SITE |           |        |  |  |
| 16.                  | Whether the Site is vacant  | Yes                                    |           |        |  |  |
| 17.                  | Plot size (As per measurement)(In Sqmt)   | 141.84                                 |           |        |  |  |
| 18.                  | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel   | No                                     |           |        |  |  |
| 19.                  | Sketch site plan showing the location of the site,<br>important land marks and connectivity with the main<br>road is enclosed. (For site not located on main road) at<br>page | YES                                    |           |        |  |  |
| 20.                  | Any other information.  | NO                                     |           |        |  |  |
| 21.                  | Verified the Amins report with/without site inspection and found correct  | Yes                                    |           |        |  |  |
| 22.                  | Land Use  | Residential                            |           |        |  |  |
| 23.                  | Road  | Yes                                    |           |        |  |  |
| 24.                  | Sewerage  | No                                     |           |        |  |  |
| 25.                  | Drainage  | No                                     |           |        |  |  |
| 26.                  | Water facility  | No                                     |           |        |  |  |
| 27.                  | Availability of drain   | No                                     |           |        |  |  |
| 28.                  | Telephone   | Yes                                    |           |        |  |  |
| 29.                  | Electricity   | Yes                                    |           |        |  |  |

| 30. | Dealing with inflammable/chemical                      | No                         |
|-----|--|----------------------------|
| 31. | Occupancy  | No                         |
| 32. | EAST   | ROAD WIDTH-3.66<br>m       |
| 33. | WEST   | PLOT NO-Vendor<br>Nij      |
| 34. | NORTH  | PLOT NO-Suchitra<br>Mahato |
| 35. | SOUTH  | PLOT NO-Rewti<br>Devi      |
| 36. | Length of the Road(In Mtr.)                            | Up to 50 meter             |
| 37. | Existing Width of the Road(In Mtr.)                    | 3.66                       |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 0                          |
| 39. | Width of the RoadWidening(In Mtr.)                     | 0                          |
| 40. | Plot area (As per deed)                                | 141.84                     |

## Site Visit Photographs :









Recommendation : Verified & found Ok Remark : ok

> Deepak Kumar Junior Engg