Chas Municipal Corporation

SITE VISIT REPORT

Proposal Details			
Owner Name	: URMILA DEVI	Site Visit Date	: 18 March, 2022
Applicant Name	: RAVI KUMAR	File No.	: CMC/BP/0065/W29/2022
Ward No.	: W29	Case Type	: New
Thana No.	: 34	Plot No.	1366
Road No. / Name	:	Registration No.	: CMC/DFTMN/0024/2017

Site Visit Checklist					
Description	As On Site	Objection	Remark		
Whether Existing at Site	Yes				
Whether connected with an existing public road	Yes				
Status of road	Public				
Nature of Road	Kutchha				
Width of approach road	6.1 M				
Whether road side drain exists	No				
if Whether road side drain exists is No - Distance from nearest drain	30 m				
if Whether road side drain exists is No - easibility to connect	No				
if Whether road side drain exists is No - Scope of widening of road	NO				
Whether the site is at road junction	No				
Level of site in relation to approach road	0.01				
Whether the area is subject to	NA				
Whether the locality is	Developing				
Distance of the plot from the nearest temple/ monument / Airport/ Other important building	NO				
The vertical and horizontal distance from 33 KV/11 KV electric line	HIGH TENSION WIRE IS NOT AT SITE				
Whether the Site is vacant	Yes				
Plot size (As per measurement)(In Sqmt)	121.44				
Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No				
Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	YES				
Any other information.	NO				
	Yes				
Land Use	Residential				
Road	Yes				
Sewerage	No				
Drainage	No				
Water facility	No				
Availability of drain	No				
Telephone	Yes				
Electricity	Yes				
	DescriptionWhether Existing at SiteWhether connected with an existing public roadStatus of roadNature of RoadWidth of approach roadWhether road side drain existsif Whether road side drain exists is No - Distance from nearest drainif Whether road side drain exists is No - easibility to connectif Whether road side drain exists is No - Scope of widening of roadWhether the site is at road junctionLevel of site in relation to approach roadWhether the area is subject toWhether the locality isDistance of the plot from the nearest temple/ monument / Airport/ Other important buildingThe vertical and horizontal distance from 33 KV/11 KV electric lineWhether the Site is vacantPlot size (As per measurement)(In Sqmt)Whether the applicant encroached the Govt. land/road land/any other land/drainage channelSketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageAny other information.Verified the Amins report with/without site inspection and found correctLand UseRoadSewerageDrainageWater facility	DescriptionAs On SiteWhether Existing at SiteYesWhether connected with an existing public roadYesStatus of roadPublicNature of RoadKutchhaWidth of approach road6.1 MWhether road side drain existsNoif Whether road side drain exists is No - Distance from nearest drain30 mif Whether road side drain exists is No - easibility to connectNoconnectNoif Whether road side drain exists is No - Scope of widening of roadNoWhether the site is at road junctionNoLevel of site in relation to approach road0.01Whether the area is subject toNAWhether the locality isDevelopingDistance of the plot from the nearest temple/ monument / Airport/ Other important buildingNOThe vertical and horizontal distance from 33 KV/11 KV electric lineHIGH TENSION WIRE IS NOT AT SITEWhether the Site is vacantYesPlot size (As per measurement)(In Sqmt)121.44Whether the applicant encroached the Goxt. land/road land/any other land/drainage channelNoSketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageNOVerified the Amins report with/without site inspection and found correctNoLand UseResidentialNoRoadYesSewerageNoDrainageNoAvailability of drainNoTelephone<	DescriptionAs On SiteObjectionWhether Existing at SiteYesWhether connected with an existing public roadYesStatus of roadPublicNature of RoadKutchhaWidth of approach road6.1 MWhether road side drain existsNoif Whether road side drain exists is No - Distance from nearest drain30 mif Whether road side drain exists is No - easibility to connectNoConnectNoWhether road side drain exists is No - Scope of widening of roadNoWhether the asist is at road junctionNoLevel of site in relation to approach road0.01Whether the locality isDevelopingDistance of the plot from the nearest temple/ monument / Airport/ Other important buildingNoThe vertical and horizontal distance from 33 KV/11 KV electric lineHIGH TENSION WIRE IS NOT AT SITEWhether the site is vacantYesPlot size (As per measurement)(In Sqmt)121.44Whether land narks and connectivity with the main road is enclosed. (For site not located on main road) at pageNoAny other information.NOVerified the Amins report with/without site inspection and found correctNoLand UseResidentialRoadYesSewerageNoOrainageNoAny other information.NoVerified the Amins report with/without site inspection and found correctLand UseResidentialRoadYesSewerageNo		

30.	Dealing with inflammable/chemical	No
31.	Occupancy	No
32.	EAST	PLOT NO-VENDOR NIJJ
33.	WEST	ROAD WIDTH-6.10 M ROAD
34.	NORTH	PLOT NO-VENDOR NIJJ
35.	SOUTH	PLOT NO-MUNNI DEVI
36.	Length of the Road(In Mtr.)	Up to 50 meter
37.	Existing Width of the Road(In Mtr.)	6.1
38.	Proposed Width of the Road as per Master Plan(In Mtr.)	0
39.	Width of the RoadWidening(In Mtr.)	0
40.	Plot area (As per deed)	121.44

Site Visit Photographs :











Recommendation : Verified & found Ok Remark : ok

> Deepak Kumar Junior Engg