Chas Municipal Corporation

SITE VISIT REPORT

Proposal Details					
: SITAPATI DEVI	Site Visit Date	: 24 June, 2022			
: AMRIT KUMAR MAHATO	File No.	: CMC/BP/0151/W30/2022			
: W30	Case Type	: New			
: 35	Plot No.	23 NEW PLOT NO 81			
: BANDHGORA	Registration No.	: CMC/DFTMN/0004/2019			
	: AMRIT KUMAR MAHATO : W30 : 35	: AMRIT KUMAR MAHATOFile No.: W30Case Type: 35Plot No.			

#DescriptionAs On SiteObjectionRemark1Whethe Existing SiteSeries <th></th> <th colspan="6">Site Visit Checklist</th>		Site Visit Checklist					
Instruction Whether connected with an existing public road Yes 3. Status of road Public Image: Connected with an existing public road 4. Nature of Road Kutchha Image: Connected with an existing public road 5. Width of approach road 4.57 m Image: Connected with an existing public road 6. Whether road side drain exists No Image: Connected with an existing public road 7. if Whether road side drain exists is No - Distance from nearest drain 1000 m 8. if Whether road side drain exists is No - Scope of widening of road No 9. if Whether road side drain exists is No - Scope of widening of road No 10. Whether the area is subject to NA 11. Level of site in relation to approach road 0.01 12. Whether the locality is Developing 13. Whether the locality is No 14. Distance of the plot from the nearest temple/ monumert / Airport / Chrier important building No 15. The vertical and horizontal distance from 33 KV/11 KV electric is NoT AT stres Image: Connectric Y with the main road is electric line 16. Whether the splicant encroacted the Govt. land/road and electric line No Image: Connectric Y with the main road is elocased on thai orda) at pade 17.	#	Description	As On Site	Objection	Remark		
3 Status of road Public 4 Nature of Road Kutchha 5 Width of approach road 4.57 m 6 Whether road side drain exists No 7 If Whether road side drain exists is No - Distance from connersest drain. 1000 m 8 if Whether road side drain exists is No - easibility to conner No 9 if Whether road side drain exists is No - Scope of widening of road No 10 Whether the site is a troad junction No 11 Level of site in relation to approach road 0.01 12 Whether the area is subject to NA 13 Whether the locality is Developing 14 Distance of the plot from the nearest temple/ monument / Airport/ Other important building NO 15 The vertical and horizontal distance from 33 KV/11 KV HIGH TENSION WIRE IS NOT AT SITE 16 Whether the Site is vacant Yes 17 Plot size (As per measurement)(In Sqmt) 161.93 18 Whether the applicant encroached the Govt. land/road land/any other land/rainage channel No 19 Sketch site plan showing the location of the site, important land marks and connectivity with the main road at land/any other land/ariange channel No 20 Any other information. NO Image <	1.	Whether Existing at Site	Yes				
Nature of Road Kutchha Nutch of approach road 4.57 m Width of approach road 4.57 m Whether road side drain exists No Mutch of approach road 1000 m Wether road side drain exists is No - Distance from nearest drain 1000 m Mutch of approach road side drain exists is No - Scope of connect No Mutch of road No Wether the side is at road junction No Wether the site is at road junction No Wether the area is subject to NA Wether the area is subject to NA Wether the locality is Developing Distance of the plot from the nearest temple/ monument / Airport/ Other important building NO Mutch wether the site is vacant Yes Wether the site is vacant Yes Mutch wether the applicant encroached the Goxt. land/road land/any other land/drainage channel No Mutch wether site plans howing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page Yes Any other information. NO Image And use Residential Image Sewerage No <td>2.</td> <td>Whether connected with an existing public road</td> <td>Yes</td> <td></td> <td></td>	2.	Whether connected with an existing public road	Yes				
Nature of Network Nature Witch of approach road 4.57 m Whether road side drain exists No Whether road side drain exists is No - Distance from nearest drain 1000 m If Whether road side drain exists is No - easibility to connect No If Whether road side drain exists is No - Scope of widening of road No Whether the site is at road junction No Whether the site is at road junction No Whether the area is subject to NA Use of site in relation to approach road 0.01 Whether the area is subject to NA Whether the locality is Developing Distance of the plot from the nearest temple/ monument / Airport/ Other important building NO Multiple is a cant Yes Vester the applic and norizontal distance from 33 KV/11 KV electric line HIGH TENSION WIRE IS NOT AT SITE Plot size (As per measurement)(In Sqmt) 161.93 Important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page Any other information. NO Important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page Any other information.	3.	Status of road	Public				
No No Whether road side drain exists No If Whether road side drain exists is No - Distance from nearest drain 1000 m If Whether road side drain exists is No - easibility to connect No If Whether road side drain exists is No - Scope of widening of road No Whether the site is at road junction No Whether the site is at road junction No Whether the area is subject to NA Whether the locality is Developing Whether the locality is Developing Ib Distance of the plot from the nearest temple/monumert / Alzport/ Other important building NO Ib Distance of the plot from the nearest temple/monumert / Alzport/ Other important building NO Ib Whether the Site is vacant Yes Ib State the size (As per measurement)(In Sqmt) 161.93 Ib Whether the applicant encroached the Govt. land/road page No Ib Any other information. NO Ib Sketch site plan showing the location of the site, inportant land marks and connectivity with the main road is enclosed. (For site not located on main road) at page YES Ib Any other information. NO Important land marks and connecti	4.	Nature of Road	Kutchha				
Interface of the base of the base. In the base of the base of the base of the base	5.	Width of approach road	4.57 m				
nearest drain1000 m8.if Whether road side drain exists is No - easibility to connectNo9.if Whether road side drain exists is No - Scope of widening of roadNo10.Whether the site is at road junctionNo11.Level of site in relation to approach road0.0112.Whether the area is subject toNA13.Whether the locality isDeveloping14.Distance of the plot from the nearest temple/ monument / Airport/ Other important buildingNO15.The vertical and horizontal distance from 33 KV/11 KV electric lineHIGH TENSION WIRE IS NOT AT SITE is NOT AT SITE is NOT AT SITE is not static and horizontal distance from 33 KV/11 KV electric lineHIGH TENSION WIRE IS NOT AT SITE is NOT AT SITE is NOT AT 	6.	Whether road side drain exists	No				
connectNONO9.if Whether road side drain exists is NO - Scope of widening of roadNONO10.Whether the site is at road junctionNOImage: Scope of widening of roadNO11.Level of site in relation to approach road0.01Image: Scope of widening of roadNO12.Whether the area is subject toNAImage: Scope of widening of the plot from the nearest temple/ monument / Airport/ Other important buildingNOImage: Scope of NO15.The vertical and horizontal distance from 33 KV/11 KV electric lineHIGH TENSION WIRE IS NOT AT SITEImage: Scope of SITEImage: Scope of NO16.Whether the Site is vacantYesImage: Scope of NONo17.Plot size (As per measuremet)(In Sqmt)161.93Image: Scope of NO18.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNOImage: Scope of NO20.Any other information.NOImage: Scope of YESNo21.Verified the Amins report with/without site inspection and found correctNOImage: Scope of YES22.Land UseResidentialImage: Scope of YESImage: Scope of YES23.RoadYesImage: Scope of YESImage: Scope of YES24.SewerageNoImage: Scope of YESImage: Scope of YES25.DrainageNoImage: Scope of YESImage: Scope of YES26.Water facility	7.		1000 m				
widening of roadNONO10Whether the site is at road junctionNoImage: Constraint of the site is at road junctionNo11Level of site in relation to approach road0.01Image: Constraint of the site is at relation to approach road0.0111Whether the area is subject toNAImage: Constraint of the site is at relation to approach road0.01Image: Constraint of the site is at relation to approach road13Whether the area is subject toNAImage: Constraint of the site is at relation to approach roadDeveloping14Distance of the plot from the nearest temple/ monument / Airport/ Other important buildingNOImage: Constraint of the site is approach road is an of the site is a constraint of the site is a constraint of the site is a constraint of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageNOImage: Constraint of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYesImage: Constraint of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYesImage: Constraint of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYesImage: Constraint of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYesImage: Constraint of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at 	8.		No				
Indected to the barry of the	9.		NO				
12. Whether the area is subject to NA Image: Contemportant Strengther Strengten Strengther Strengther Strengther Strengthe	10.	Whether the site is at road junction	No				
Interface the locality isInterface13.Whether the locality isDeveloping14.Distance of the plot from the nearest temple/ monument / Airport/ Other important buildingNO15.The vertical and horizontal distance from 33 KV/11 KV electric lineHIGH TENSION WIRE IS NOT AT SITE16.Whether the Site is vacantYes17.Plot size (As per measurement)(In Sqmt)161.9318.Whether the applicant encroached the Govt. land/road land/ary other land/drainage channelNo19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageNO20.Any other information.NO21.Verified the Amins report with/without site inspection and found correctYes22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityNo27.Availability of drainNo28.TelephoneYes	11.	Level of site in relation to approach road	0.01				
14. Distance of the plot from the nearest temple/ monument / Airport/ Other important building NO 15. The vertical and horizontal distance from 33 KV/11 KV electric line HIGH TENSION WIRE IS NOT AT SITE 16. Whether the Site is vacant Yes 17. Plot size (As per measurement)(In Sqmt) 161.93 18. Whether the applicant encroached the Govt. land/road land/any other land/drainage channel No 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page YES 20. Any other information. NO 21. Verified the Amins report with/without site inspection and found correct Yes 22. Land Use Residential 23. Road Yes 24. Sewerage No 25. Drainage No 26. Water facility No 27. Availability of drain No 28. Telephone Yes	12.	Whether the area is subject to	NA				
monument / Airport/ Other important buildingNO15.The vertical and horizontal distance from 33 KV/11 KV electric lineHIGH TENSION WIRE IS NOT AT STEE16.Whether the Site is vacantYes17.Plot size (As per measurement)(In Sqmt)161.9318.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNo19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYES20.Any other information.NO21.Verified the Amins report with/without site inspection and found correctResidential22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityNo27.Availability of drainNo28.TelephoneYes	13.	Whether the locality is	Developing				
Ine vertical and nonzontal distance from 33 KV/11 KV electric lineWIRE IS NOT AT SITE16.Whether the Site is vacantYes17.Plot size (As per measurement)(In Sqmt)161.9318.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNo19.Sketch site plan showing the location of the site, 	14.		NO				
17.Plot size (As per measurement)(In Sqmt)161.93Image: Constraint of the section of	15.		WIRE IS NOT AT				
18. Whether the applicant encroached the Govt. land/road land/any other land/drainage channel No 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page YES 20. Any other information. NO 21. Verified the Amins report with/without site inspection and found correct Yes 22. Land Use Residential 23. Road Yes 24. Sewerage No 25. Drainage No 26. Water facility No 27. Availability of drain No 28. Telephone Yes	16.	Whether the Site is vacant	Yes				
Iand/any other land/drainage channelNO19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYES20.Any other information.NO21.Verified the Amins report with/without site inspection and found correctYes22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityNo27.Availability of drainNo28.TelephoneYes	17.	Plot size (As per measurement)(In Sqmt)	161.93				
important land marks and connectivity with the main pageYESYES20Any other information.NO21.Verified the Amins report with/without site inspection and found correctYes22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityNo27.Availability of drainNo28.TelephoneYes	18.		No				
21.Verified the Amins report with/without site inspection and found correctYesImage: Constant site inspection and found correct22.Land UseResidentialImage: Constant site inspectionYes23.RoadYesImage: Constant site inspectionYes24.SewerageNoImage: Constant site inspectionNo25.DrainageNoImage: Constant site inspectionNo26.Water facilityNoImage: Constant site inspectionNo27.Availability of drainNoImage: Constant site inspectionNo28.TelephoneYesImage: Constant site inspectionYes	19.	important land marks and connectivity with the main road is enclosed. (For site not located on main road) at	YES				
found correctresres22.Land UseResidentialResidential23.RoadYesImage24.SewerageNoImage25.DrainageNoImage26.Water facility of drainNoImage27.Availability of drainNoImage28.TelephoneYesImage	20.	Any other information.	NO				
23.RoadYesImage24.SewerageNoImage25.DrainageNoImage26.Water facilityNoImage27.Availability of drainNoImage28.TelephoneYesImage	21.		Yes				
24.SewerageNoImage25.DrainageNoImage26.Water facilityNoImage27.Availability of drainNoImage28.TelephoneYesImage	22.	Land Use	Residential				
25.DrainageNoImage26.Water facilityNoImage27.Availability of drainNoImage28.TelephoneYesImage	23.	Road	Yes				
26.Water facilityNo27.Availability of drainNo28.TelephoneYes	24.	Sewerage	No				
27. Availability of drain No 28. Telephone Yes	25.	Drainage	No				
28. Telephone Yes	26.	Water facility	No				
	27.	Availability of drain	No				
29. Electricity Yes	28.	Telephone	Yes				
	29.	Electricity	Yes				

30.	Dealing with inflammable/chemical	No
31.	Occupancy	No
32.	EAST	CTS NO- PART OF PLOT
33.	WEST	ROAD WIDTH-4.57 MTR WIDE ROAD
34.	NORTH	PLOT NO-PLOTING NO-04
35.	SOUTH	PLOT NO-PLOTING NO-02
36.	Length of the Road(In Mtr.)	Up to 50 meter
37.	Existing Width of the Road(In Mtr.)	4.57
38.	Proposed Width of the Road as per Master Plan(In Mtr.)	0
39.	Width of the RoadWidening(In Mtr.)	0
40.	Plot area (As per deed)	161.93

Site Visit Photographs :









Recommendation : Verified & found Ok Remark : ok

> Pawan Pandey Junior Engg