Chas Municipal Corporation

SITE VISIT REPORT

Proposal Details					
Owner Name	: SHAIL JHA	Site Visit Date	: 03 November, 2023		
Applicant Name	: AMRIT KUMAR MAHATO	File No.	: CMC/BP/0271/W02/2023		
Ward No.	: W02	Case Type	: New		
Thana No.	: 30	Plot No.	1274		
Road No. / Name	: K.K. SINGH COLONY CHIRA CHAS	Registration No.	: CMC/DFTMN/0004/2019		

Induct of the order of the production of the production of the production of the product of the		Site Visit Checklist					
2. Whether connected with an existing public road Yes 3. Status of road Public Image: Connected with an existing public road 4. Nature of Road Kutchha Image: Connected with an existing public road 5. Width of approach road 6.10 M Image: Connected with an exists is No - Distance from present drain 6. Whether road side drain exists is No - Distance from present drain 20.0 M Image: Connected with an exists is No - Scope of No 9. If Whether road side drain exists is No - Scope of No No Image: Connected with an exist is No - Scope of No 10. Whether the act is a troad junction No Image: Connected with an exist is No - Scope of No 11. Level of site in relation to approach road 0.01 M Image: Connected with an exist is No - Scope of No 12. Whether the act is a troad junction No Image: Connected with an exist is No - Scope of No 13. Whether the locality is Developed Image: Connected with an exist is No - Scope of No 14. Distance of the plot from the nearest temple/ mountement / Airport/ Other important building No 15. The vertical and horizontal distance from 33 KV/11 KV NNO HT WIRE AT SITE 15.	#	Description	As On Site	Objection	Remark		
3. Status of road Public 4. Nature of Road Kutchha 5. Width of approach road 6.10 M 6. Whether road side drain exists No 7. If Whether road side drain exists is No - Distance from context 200.0 M 8. If Whether road side drain exists is No - easibility to context No 9. If Whether road side drain exists is No - Scope of Woldening of road No 10. Whether the site is at road junction No 11. Level of site in relation to approach road 0.01 M 12. Whether the locality is Developed 13. Whether the locality is Developed 14. Distance of the plot from the nearest temple/ monument / Airport/ Other important building NO NO 15. Whether the site is vacant Yes 16. Whether the site is vacant Yes 17. Plot size (As per measurement)(In Sqmt) 111.38 18. Whether the site is vacant Yes 19. Sketch site plan showing the location of the site, important building nod al and/any other land/ariage channel No 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main road is acholesd. (For site and horizated on main road) is acholesd. No 20. Any other information. NO Imag	1.	Whether Existing at Site	Yes				
4. Nature of Road Kutchha 5. Width of approach road 6.10 M 6. Whether road side drain exists No 7. If Whether road side drain exists is No - Distance from nearest drain 200.0 M 8. If Whether road side drain exists is No - easibility to connect No 9. If Whether road side drain exists is No - Scope of widening of road No 10. Whether the site is at road junction No 11. Level of site in relation to approach road 0.01 M 12. Whether the size is at road junction No 13. Whether the locality is Developed 14. Distance of the plot from the nearest temple/ monument / Airport Other important building NO 15. The vertical and horizontal distance from 33 KV/11 KV sleetch: line NNO HT WIRE AT SITE 16. Whether the site is accant Yes Yes 17. Plot size (As per measurement)(In Sqmt) 111.38 Interview of the not connect of the site, important and connectivity with the main road is enclosed. (For site not located on main road) at page No 18. Whether the applicant encroached the Govt. land/road land/any other land/rains encorn with/without site inspection and found correct No 19. Sketch site plan showing the location of the site, import and cornect with with the main road is enclosed. (For site not located on main road) at page <	2.	Whether connected with an existing public road	Yes				
Nature of read Sector Witch of approach road 6.10 M 6 Whether road side drain exists No 7 if Whether road side drain exists is No - Distance from nearest drain 200.0 M 8 if Whether road side drain exists is No - easibility to connect. No 9 if Whether road side drain exists is No - Scope of widening of road No 10. Whether tread side drain exists is No - Scope of widening of road No 11. Level of site in relation to approach road 0.01 M 12. Whether the area is subject to NA 13. Whether the locality is Developed 14. Distance of the plot from the nearest temple/ monument / Airport / Other important building NO 15. The vertical and horizontal distance from 33 KV/11 KV NNO HT WIRE AT SITE 16. Whether the aplicant encroached the Govt. land/road land/any other land/rainage channel No 17. Plot size (As per measurement)(In Sqmt) 111.38 18. Whether the aplicant encroached the Govt. land/road land/any other land/aris and connectivity with the main road is enclosed. (For site not located on main road) at page No	3.	Status of road	Public				
Note of performance Note of the performance Whether road side drain exists No If Whether road side drain exists is No - Distance from an earest drain 200.0 M If Whether road side drain exists is No - easibility to connect No If Whether road side drain exists is No - Scope of widening of road No If Whether road side drain exists is No - Scope of widening of road No IV Wether the site is at road junction No IV Wether the site is at road propach road 0.01 M IV Wether the site is at road junction No IV Wether the site is at road junction No IV Wether the site is at road propach road 0.01 M IV Wether the locality is Developed IV Whether the locality is Developed IV Distance of the plot from the nearest temple/ monument / Airport/ Other important building NO IV No thread the approximation as a connectivity with the main road is enclosed the Govt. land/road land/any other land/drainage channel No IV Plot size (As per measurement)(In Sqmt) NO IV Not the plan showing the location of	4.	Nature of Road	Kutchha				
if Whether road side drain exists is No - Distance from cannect 200.0 M a. if Whether road side drain exists is No - easibility to connect No a. if Whether road side drain exists is No - easibility to connect No a. if Whether road side drain exists is No - Scope of widening of road NO 10. Whether the site is at road junction No 11. Level of site in relation to approach road 0.01 M 12. Whether the area is subject to NA 13. Whether the locality is Developed 14. Distance of the plot from the nearest temple/ monument / Airport/ Other important building NO 15. The vertical and horizontal distance from 33 KV/11 KV electric line NNO HT WIRE AT SITE 16. Whether the applicant encroached the Govt. land/road land/any other land/drainage channel No 19. Sketch site pian showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page No 20. Any other information. NO NO 21. Verified the Amins report with/without site inspection and found correct Yes Important and ank set on a set on	5.	Width of approach road	6.10 M				
nearest drain 200.0 M 8. if Whether road side drain exists is No - easibility to connect No 9. if Whether road side drain exists is No - Scope of widening of road No 10. Whether the site is at road junction No 11. Level of site in relation to approach road 0.01 M 12. Whether the area is subject to NA 13. Whether the locality is Developed 14. Distance of the plot from the nearest temple/ monumer / Airport/ Other important building NO 15. The vertical and horizontal distance from 33 KV/11 KV electric line NNO HT WIRE AT SITE 16. Whether the Site is vacant Yes 17. Plot size (As per measurement)(In Sqmt) 111.38 18. Whether the applicant encroached the Govt. land/road land/any other indn/drainage channel No 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page No 20. Any other information. NO Image: State Sta	6.	Whether road side drain exists	No				
connectNO9.if Whether road side drain exists is No - Scope of widening of roadNO10.Whether the site is at road junctionNo11.Level of site in relation to approach road0.01 M12.Whether the area is subject toNA13.Whether the locality isDeveloped14.Distance of the plot from the nearest temple/ monument / Airport/ Other important buildingNO15.The vertical and horizontal distance from 33 KV/11 KV electric lineNNO HT WIRE AT SITE16.Whether the Site is vacantYes17.Plot size (As per measurement)(In Sqmt)111.3818.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNo19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageNO20.Any other information.NOImage21.Verified the Amins report with/without site inspection and found correctNoImage22.Land UseResidentialImage23.RoadYesImage24.SewerageNoImage25.DrainageNoImage26.Water facilityYesImage27.Availability of drainYesImage28.TelephoneNoImage29.ElectricityNoImage	7.		200.0 M				
widening of roadNO10.Whether the site is at road junctionNo11.Level of site in relation to approach road0.01 M12.Whether the area is subject toNA13.Whether the locality isDeveloped14.Distance of the plot from the nearest temple/ monument / Airport/ Other important buildingNO15.The vertical and horizontal distance from 33 KV/11 KV electric lineNNO HT WIRE AT SITE16.Whether the Site is vacantYes17.Plot size (As per measurement)(In Sqmt)111.3818.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNo19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageNO20.Any other information.NOImage: Section and found correct21.Verified the Amins report with/without site inspection and found correctYes22.Land UseResidentialImage: Section and Found correct23.RoadYesImage: Section and Found correct24.SeverageNoImage: Section and Found correct25.DrainageNoImage: Section and Found correct26.Water facilityYesImage: Section and Found correct27.Availability of drainYesImage: Section and Found correct28.TelephoneNoImage: Section and Found correct	8.		No				
Induct the orbit of the probability of	9.		NO				
22. Whether the area is subject to NA 33. Whether the locality is Developed 44. Distance of the plot from the nearest temple/ monument / Airport/ Other important building NO 15. The vertical and horizontal distance from 33 KV/11 KV electric line NNO HT WIRE AT SITE 16. Whether the Site is vacant Yes 17. Plot size (As per measurement)(In Sqmt) 111.38 18. Whether the applicant encroached the Govt. land/road land/any other land/drainage channel No 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page NO 20. Any other information. NO 21. Verified the Amins report with/without site inspection and found correct Yes 22. Land Use Residential 23. Road Yes 24. Sewerage No 25. Drainage No 26. Water facility Yes 27. Availability of drain Yes 28. Telephone No 29. Electricity No	10.	Whether the site is at road junction	No				
Interfact the locality is Interfact the locality is 13. Whether the locality is Developed 14. Distance of the plot from the nearest temple/ monument / Airport/ Other important building NO 15. The vertical and horizontal distance from 33 KV/11 KV electric line NNO HT WIRE AT SITE 16. Whether the Site is vacant Yes 17. Plot size (As per measurement)(In Sqmt) 111.38 18. Whether the applicant encroached the Govt. land/road land/any other land/drainage channel No 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page NO 20. Any other information. NO 21. Verified the Amins report with/without site inspection and found correct Yes 22. Land Use Residential 23. Road Yes 24. Sewerage No 25. Drainage No 26. Water facility Yes 27. Availability of drain Yes 28. Telephone No 29. Electricity No	11.	Level of site in relation to approach road	0.01 M				
14. Distance of the plot from the nearest temple/ monument / Airport/ Other important building NO 15. The vertical and horizontal distance from 33 KV/11 KV electric line NNO HT WIRE AT SITE 16. Whether the Site is vacant Yes 17. Plot size (As per measurement)(In Sqmt) 111.38 18. Whether the applicant encroached the Govt. land/road land/any other land/drainage channel No 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page NO 20. Any other information. NO 21. Verified the Amins report with/without site inspection and found correct Yes 22. Land Use Residential 23. Road Yes 24. Sewerage No 25. Drainage No 26. Water facility Yes 27. Availability of drain Yes 28. Telephone No 29. Electricity No	12.	Whether the area is subject to	NA				
monument / Airport/ Other important buildingNO15.The vertical and horizontal distance from 33 KV/11 KV electric lineNNO HT WIRE AT SITE16.Whether the Site is vacantYes17.Plot size (As per measurement)(In Sqmt)111.3818.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNo19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageNO20.Any other information.NO21.Verified the Amins report with/without site inspection and found correctResidential22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityYes27.Availability of drainYes28.TelephoneNo29.ElectricityNo	13.	Whether the locality is	Developed				
electric lineSITE16.Whether the Site is vacantYes17.Plot size (As per measurement)(In Sqmt)111.3818.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNo19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageNO20.Any other information.NOImage: Connectivity with the main found correct21.Verified the Amins report with/without site inspection an found correctYes22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityYes27.Availability of drainYes28.TelephoneNo29.ElectricityNo	14.		NO				
Inducts one of the brackIntervention17.Plot size (As per measurement)(In Sqmt)111.3818.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNo19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageNO20.Any other information.NO21.Verified the Amins report with/without site inspection and found correctYes22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityYes27.Availability of drainYes28.TelephoneNo29.ElectricityNo	15.		-				
18. Whether the applicant encroached the Govt. land/road land/any other land/drainage channel No 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page NO 20. Any other information. NO 21. Verified the Amins report with/without site inspection and found correct Yes 22. Land Use Residential 23. Road Yes 24. Sewerage No 25. Drainage No 26. Water facility Yes 27. Availability of drain Yes 28. Telephone No 29. Electricity No	16.	Whether the Site is vacant	Yes				
Iand/any other land/drainage channelNO19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageNO20.Any other information.NO21.Verified the Amins report with/without site inspection and found correctYes22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityYes27.Availability of drainYes28.TelephoneNo29.ElectricityNo	17.	Plot size (As per measurement)(In Sqmt)	111.38				
important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageNOImage20.Any other information.NOImage21.Verified the Amins report with/without site inspection and found correctYesImage22.Land UseResidentialImage23.RoadYesImageImage24.SewerageNoImageImage25.DrainageNoImageImage26.Water facilityYesImageImage27.Availability of drainYesImageImage28.TelephoneNoImageImage29.ElectricityNoImageImage	18.		No				
21.Verified the Amins report with/without site inspection and found correctYesImage: Second sec	19.	important land marks and connectivity with the main road is enclosed. (For site not located on main road) at	NO				
found correctres22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityYes27.Availability of drainYes28.TelephoneNo29.ElectricityNo	20.	Any other information.	NO				
23.RoadYesImage24.SewerageNoImage25.DrainageNoImage26.Water facilityYesImage27.Availability of drainYesImage28.TelephoneNoImage29.ElectricityNoImage	21.		Yes				
24.SewerageNoImage25.DrainageNoImage26.Water facilityYesImage27.Availability of drainYesImage28.TelephoneNoImage29.ElectricityNoImage	22.	Land Use	Residential				
25. DrainageNo26. Water facilityYes27. Availability of drainYes28. TelephoneNo29. ElectricityNo	23.	Road	Yes				
26.Water facilityYes27.Availability of drainYes28.TelephoneNo29.ElectricityNo	24.	Sewerage	No				
27. Availability of drain Yes 28. Telephone No 29. Electricity No	25.	Drainage	No				
28. Telephone No 29. Electricity No	26.	Water facility	Yes				
29. Electricity No	27.	Availability of drain	Yes				
	28.	Telephone	No				
30. Dealing with inflammable/chemical No	29.	Electricity	No				
	30.	Dealing with inflammable/chemical	No				

31.	Occupancy	No
32.	EAST	BACHANDIH DHAR
33.	WEST	6.10 MTR WIDE ROAD
34.	NORTH	PART OF PLOT
35.	SOUTH	RAJIV KUMAR UPADHYAY
36.	Length of the Road(In Mtr.)	Up to 50 meter
37.	Existing Width of the Road(In Mtr.)	6.1
38.	Proposed Width of the Road as per Master Plan(In Mtr.)	0
39.	Width of the RoadWidening(In Mtr.)	0
40.	Plot area (As per deed)	139.26

Site Visit Photographs :







 Chira Chas, Bokaro Steel City, 827013, J.H. India

 utinude
 Longitude

 25.6561° N
 86.1831° E

 boxil 12.2915 PM
 Altitude 202 mittes

 dvf ros915 NA
 Twesky 1093/022



Recommendation : Verified & found Ok Remark : OK

> Bishwas Kumar Junior Engg