Jamshedpur NAC

SITE VISIT REPORT


Proposal Details							
Owner Name	: Sri. SOUMIN BISWAS AND Sri. DEBOJYOTI	Site Visit Date	: 31 August, 2017				
Applicant Name	: BATISH KUMAR	File No.	: JNAC/BP/0056/W11/2017				
Ward No.	: W11	Case Type	: New				
Thana No.	: 9	Plot No.	1413				
Road No. / Name	: NEW SITARAMDERA AREA	Registration No.	: JNAC/DFTMN/0004/2017				

	Site Visit Checklist					
#	Description	As On Site	Objection	Remark		
1.	Approach Road					
2.	Whether Existing at Site	Yes				
3.	Whether connected with an existing public road	Yes				
4.	Status of road	Public				
5.	Nature of Road	Concrete				
6.	Width of approach road	12.1				
7.	Whether road side drain exists	Yes				
8.	if Whether road side drain exists is Yes - Width	.35				
9.	if Whether road side drain exists is Yes - Nature	Concrete				
10.	if Whether road side drain exists is Yes - Whether connected to	Public Drain				
11.	Site Situation					
12.	Whether the site is at road junction	No				
13.	Level of site in relation to approach road	.10 UP FROM ERL				
14.	Whether the area is subject to	Low lying land				
15.	Whether the locality is	Developing				
16.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	500 Mtrs.				
17.	The vertical and horizontal distance from 33 KV/11 KV electric line	1.5 KMS				
18.	Site Details					
19.	Whether the Site is vacant	No				
20.	if Whether the Site is vacant No - Stage of construction	1				
21.	if Whether the Site is vacant No - No of Storey	1				
22.	if Whether the Site is vacant No - Nature of construction	RCC				
23.	if Whether the Site is vacant No - Sketch enclosed at page	Yes				
24.	Plot size (As per measurement)(In Sqmt)	111.36				
25.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No				
26.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	ATTACHED				
27.	Any other information.	PROVIDED				
28.	Verification Details					
29.	Verified the Amins report with/without site inspection and found correct	Yes				
30.	If No, Reason	NA				

31.	Verified the cadastral map	
32.	Land Use	Residential
33.	Existing off site Physical Infrastructure:	
34.	Road	Yes
35.	Sewerage	Yes
36.	Drainage	Yes
37.	Water facility	Yes
38.	Availability of drain	Yes
39.	Telephone	Yes
40.	Electricity	Yes
41.	Risk Parameter	
42.	Dealing with inflammable/chemical	No
43.	Occupancy	Yes
44.	Site Surrounded by (physical features)	
45.	EAST	4.27 M WIDE ALLEY
46.	WEST	OTHERS HOLDING
47.	NORTH	ALLEY
48.	SOUTH	ROAD
49.	Length of the Road(In Mtr.)	Exceeding 400 meter and upto 500 meter
50.	Existing Width of the Road(In Mtr.)	12.1
51.	Proposed Width of the Road as per Master Plan(In Mtr.)	12.1
52.	Width of the RoadWidening(In Mtr.)	0.0001

Site Visit Photographs :







Recommendation : Verified & found Ok Remark : Site inspection done and report submitted.

> Mahendra Kumar Pradhan Junior Engg