Jamshedpur NAC

SITE VISIT REPORT

Prop	osal Details							
Owner Name Applicant Name		: SMT MEDLIN KARUNA SUNDI & SRI : NAVEEN J SUNDI : Anoop Kumar	Site Visit Date File No.	: 02 March, 2018 : JNAC/BP/0002/W1/2018				
Ward No. : W1		Case Type	: New					
Thana No. : 1155		Plot No.	5892					
Road	d No. / Name	: CHRISTIAN BASTI , SONARI, JAMSHEDPUR	Registration No.	: JNAC/ENG/000	5/2016			
	Site Visit Checklist							
#		Description	As On Site	Objection	Remark			
1.	Approach Road	1						
2.	Whether Existing at Site		Yes					
3.	Whether connected with an existing public road		Yes					
4.	Status of road		Public					
5.	Nature of Road		Blacktop					
6.	Width of approach road		8.00					
7.	Whether road side drain exists		Yes					
8.	if Whether roa	if Whether road side drain exists is Yes - Width						
9.	if Whether roa	d side drain exists is Yes - Nature	Concrete					
-	if Whether road connected to	d side drain exists is Yes - Whether	Public Drain					
11.	Site Situation							
12.	Whether the si	ite is at road junction	No					
13.	Level of site in	relation to approach road	100 MM UP					
14.	Whether the area is subject to		Low lying land					
15.	Whether the locality is		Developing					
	Distance of the plot from the nearest temple/ monument / Airport/ Other important building		600 MM					
	The vertical and horizontal distance from 33 KV/11 KV electric line		1.5 KM					
18.	Site Details							
19.	Whether the S	ite is vacant	No					
20.	if Whether the	Site is vacant No - Stage of construction	1					
21.	if Whether the	Site is vacant No - No of Storey	01					
22.	if Whether the	Site is vacant No - Nature of construction	RCC					
23.	if Whether the page	Site is vacant No - Sketch enclosed at	No					
24.	Plot size (As pe	er measurement)(In Sqmt)	148.6					
	land/any other	pplicant encroached the Govt. land/road land/drainage channel	No					
	important land	n showing the location of the site, I marks and connectivity with the main ed. (For site not located on main road) at	GIVEN					
27.	Any other info	rmation.	GIVEN					
28.	Verification De	tails						
	Verified the An found correct	nins report with/without site inspection and	Yes					
30.	Verified the ca	dastral map						

31.	Land Use	Residential	
32.	Existing off site Physical Infrastructure:		
33.	Road	Yes	
34.	Sewerage	Yes	
35.	Drainage	Yes	
36.	Water facility	Yes	
37.	Availability of drain	Yes	
38.	Telephone	Yes	
39.	Electricity	Yes	
40.	Risk Parameter		
41.	Dealing with inflammable/chemical	No	
42.	Occupancy	Yes	
43.	Site Surrounded by (physical features)		
44.	EAST	OTHERS PLOT	
45.	WEST	OTHERS PLOT	
46.	NORTH	ROAD	
47.	SOUTH	ALLEY	
48.	Length of the Road(In Mtr.)	Exceeding 50 meter and upto 100 meter	
49.	Existing Width of the Road(In Mtr.)	8	
50.	Proposed Width of the Road as per Master Plan(In Mtr.)	8	
51.	Width of the RoadWidening(In Mtr.)	0	

Site Visit Photographs :





Recommendation : Remark :

> Mahendra Kumar Pradhan Junior Engg