## **Jamshedpur NAC**

## SITE VISIT REPORT

| Proposal Details |                                   |                  |   |
|------------------|-----------------------------------|------------------|---|
| Owner Name       | : RAJ KUMAR GUPTA AND SARITA DEVI | Site Visit Date  | : 24 July, 2018                           |
| Applicant Name   | : Premendra krishna Mitra         | File No.         | : JNAC/BP/0028/W17/2018                   |
| Ward No.         | : W17                             | Case Type        | : New                                     |
| Thana No.        | : 1200                            | Plot No.         | 42,66,43,65,50,51(NEW) &                  |
| Road No. / Name  | : VIJAYA GARDENS                  | Registration No. | : 4352,4353,4379,2356,4358,<br>4371(R.S.) |

## **Site Visit Checklist** # Description As On Site Objection Remark 1. Whether Existing at Site Yes 2. Yes Whether connected with an existing public road 3. Status of road Private 4. Nature of Road Concrete 5. 8.25 Width of approach road Whether road side drain exists 6. No if Whether road side drain exists is No - Distance from 7. 500 meter nearest drain if Whether road side drain exists is No - easibility to 8. Yes connect if Whether road side drain exists is No - Scope of 9. yes widening of road 10. Whether the site is at road junction No 250 mm down 11. Level of site in relation to approach road 12. Whether the area is subject to Water logging 13. Whether the locality is Developing 14. Distance of the plot from the nearest temple/ temple 1.25 km monument / Airport/ Other important building approx The vertical and horizontal distance from 33 KV/11 KV 15. approx 1.00 km electric line 16. Whether the Site is vacant Yes 17. Plot size (As per measurement)(In Sqmt) 1279.85 Whether the applicant encroached the Govt. land/road 18. No land/any other land/drainage channel 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main given road is enclosed. (For site not located on main road) at page 20. Any other information. given 21. Verified the Amins report with/without site inspection and Yes found correct 22. Land Use Residential 23. Road Yes 24. Sewerage Yes 25. Drainage Yes 26. Water facility Yes

Yes

Yes

Yes

No

27.

28.

29.

30.

Availability of drain

Dealing with inflammable/chemical

Telephone

Electricity

| 31. | Occupancy  | Yes            |
|-----|--|----------------|
| 32. | EAST   | others plot    |
| 33. | WEST   | others plot    |
| 34. | NORTH  | alley          |
| 35. | SOUTH  | road           |
| 36. | Length of the Road(In Mtr.)                            | Up to 50 meter |
| 37. | Existing Width of the Road(In Mtr.)                    | 8.25           |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 0              |
| 39. | Width of the RoadWidening(In Mtr.)                     | 0              |

## Site Visit Photographs :





Recommendation : Remark :

> Mahendra Kumar Pradhan Junior Engg