



CHIRAG CONSULTANT & COMPANY

827 B/B SONARI MANBODH MOHALLA NEAR MARUTI SERVICE CENTER
MOB:- 9102825085 , 9279340350 Email :chiragconsultant641@gmail.com
GST NO-20BNKPK5286N1ZK

STRUCTURAL STABILITY CERTIFICATE

TO WHOMSOEVER IT MAY CONCERN

This is to inform, that I have inspected the XLRI Faculty Flats A , B & C Blocks of XLRI CAMPUS , Circuit House , Jamshedpur – 831001 which is (represented by its Trustees) at Plot No.- 87(P), 88(P), 244 , 245 ,246,247,447,449,89(P), 90(P), Sub plot No:449(P) Khata No.-2, Ward No.-6, Thana No.-1154, Mauza-Beldih, District-East Singhbhum.

The Existing Building is of Ground+2, with parking below 2 flats at the rear.An additional floor is being proposed on the existing structure in all blocks (A , B & C).

Based on the available drawings of the structure and its foundations we have checked and found that the one additional floor can be constructed as per the relevant specifications and codes

The buildings will be safe if additional one floor is added on each faculty block A , B & C. and AAC Block (As per IS Code 2185 part 3 clause no 3.2.1) to be used on floor, Stair room as well as 115mm thick Parapete wall .

This building is as per IS: 456:2000 IS: 1893:2002, IS: 13920:1993, S.P-16, and other relevant codes.

Rajesh

REGD. No-
JNAC /STU/0023/2017