Jamshedpur NAC

SITE VISIT REPORT

Proposal Details

Owner Name : DEBI DAS MUKHERJEE AND GOPAL Site Visit Date : 05 March, 2024

Applicant Name : MUKHERJEE (P. A. H. AKASH File No. : JNAC/BP/0113/W2/2023

Ward No. : W2 Case Type : New

Thana No. : 1158 Plot No. 2563 a , b , c

Road No. / Name : BHATIA BASTI CHOWK , KADMA , Registration No. : JNAC/DFTMN/0004/2017


JAMSHEDPUR

JAMSHEDPUR					
Site Visit Checklist					
#	Description	As On Site	Objection	Remark	
1.	Whether Existing at Site	Yes			
2.	Whether connected with an existing public road	Yes			
3.	Status of road	Public			
4.	Nature of Road	Blacktop			
5.	Width of approach road	7.5			
6.	Whether road side drain exists	Yes			
7.	if Whether road side drain exists is Yes - Width	300 mm wide			
8.	if Whether road side drain exists is Yes - Nature	Concrete			
9.	if Whether road side drain exists is Yes - Whether connected to	Public Drain			
10.	Whether the site is at road junction	No			
11.	Level of site in relation to approach road	approx 300 mm up			
12.	Whether the area is subject to	NA			
13.	Whether the locality is	Basti Area			
14.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	Near Chandi Baba Mandir Kadma Bhatia Basti			
15.	The vertical and horizontal distance from 33 KV/11 KV electric line	jusco Power Supply by under ground Cable line			
16.	Whether the Site is vacant	No			
17.	if Whether the Site is vacant No - Stage of construction	1			
18.	if Whether the Site is vacant No - No of Storey	1			
19.	if Whether the Site is vacant No - Nature of construction	RCC			
20.	if Whether the Site is vacant No - Sketch enclosed at page	Yes			
21.	Plot size (As per measurement)(In Sqmt)	161.75			
22.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No			
23.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	Attach			
24.	Any other information.	no			
25.	Verified the Amins report with/without site inspection and found correct	Yes			
26.	Land Use	Residential			
27.	Road	Yes			
28.	Sewerage	Yes			
29.	Drainage	Yes			

Page 1 of 4 Printed on: 04 March, 2024


30.	Water facility	Yes
31.	Availability of drain	Yes
32.	Telephone	No
33.	Electricity	Yes
34.	Dealing with inflammable/chemical	No
35.	Occupancy	Yes
36.	EAST	SunRise Tower
37.	WEST	Others plot
38.	NORTH	others plot/Part of Sunrise tower
39.	SOUTH	road
40.	Length of the Road(In Mtr.)	Up to 50 meter
41.	Existing Width of the Road(In Mtr.)	7.5
42.	Proposed Width of the Road as per Master Plan(In Mtr.)	0
43.	Width of the RoadWidening(In Mtr.)	0
44.	Plot area (As per deed)	161.76

Site Visit Photographs:






Page 2 of 4 Printed on: 04 March, 2024









Recommendation: Verified & found Ok

Remark: Field verified and found that, there is an existing old building which will be demolish before new construction, all details check list filled and submitted. It forwarded for further process.

Page 3 of 4 Printed on: 04 March, 2024

Mahendra Kumar Pradhan Junior Engg

Page 4 of 4 Printed on: 04 March, 2024