Mango NAC

SITE VISIT REPORT

Proposal Details

Owner Name : SHAKIL AHMAD Site Visit Date : 18 September, 2017

Applicant Name : L K Suman File No. : MNAC/BP/0013/W08/2017

Ward No. : W08 Case Type : New Thana No. : NA Plot No. 867

Road No. / Name : Pardih Registration No. : MNAC/ENG/0008/2016

Site Visit Checklist					
#	Description	As On Site	Objection	Remark	
1.	Approach Road				
2.	Whether Existing at Site	Yes			
3.	Whether connected with an existing public road	Yes			
4.	Status of road	Public			
5.	Nature of Road	Concrete			
6.	Width of approach road	6.7			
7.	Whether road side drain exists	Yes			
8.	if Whether road side drain exists is Yes - Width	.45 mtrs			
9.	if Whether road side drain exists is Yes - Nature	Concrete			
10.	if Whether road side drain exists is Yes - Whether connected to	Public Drain			
11.	Site Situation				
12.	Whether the site is at road junction	Yes			
13.	Level of site in relation to approach road	.45 m down wrt road lvl.			
14.	Whether the area is subject to	Low lying land			
15.	Whether the locality is	Developing			
16.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	40' from nature park			
17.	The vertical and horizontal distance from 33 KV/11 KV electric line	2 kms			
18.	Site Details				
19.	Whether the Site is vacant	Yes			
20.	Plot size (As per measurement)(In Sqmt)	300.54			
21.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No			
22.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	Attached			
23.	Any other information.	Provided			
24.	Verification Details				
25.	Verified the Amins report with/without site inspection and found correct	Yes			
26.	If No, Reason	NA			
27.	Verified the cadastral map				
28.	Land Use	Residential			
29.	Existing off site Physical Infrastructure:				
30.	Road	Yes			

Page 1 of 3 Printed on : 21 September, 2017

31.	Sewerage	No
32.	Drainage	No
33.	Water facility	Yes
34.	Availability of drain	Yes
35.	Telephone	No
36.	Electricity	Yes
37.	Risk Parameter	
38.	Dealing with inflammable/chemical	No
39.	Occupancy	Yes
40.	Site Surrounded by (physical features)	
41.	EAST	Other's plot
42.	WEST	Road
43.	NORTH	Road
44.	SOUTH	Other's plot
45.	Length of the Road(In Mtr.)	Exceeding 250 meter and upto 300 meter
46.	Existing Width of the Road(In Mtr.)	6.7
47.	Proposed Width of the Road as per Master Plan(In Mtr.)	7.5
48.	Width of the RoadWidening(In Mtr.)	0.8

Site Visit Photographs:





Page 2 of 3 Printed on: 21 September, 2017







Recommendation: Verified & found Ok

 $\textbf{Remark} \hspace{0.2cm} : \hspace{0.2cm} \textbf{Site inspection done and report submitted}.$

Gajendar Kumar Junior Engg

Page 3 of 3 Printed on: 21 September, 2017