Mango NAC

SITE VISIT REPORT

Proposal Details						
Owner Name	: Sri. RAJENDRA PRASAD	Site Visit Date	: 14 September, 2017			
Applicant Name	: MUKESH KUMAR	File No.	: MNAC/BP/0010/W09/2017			
Ward No.	: W09	Case Type	: New			
Thana No.	: 1643	Plot No.	1917,1918			
Road No. / Name	: DIMNA BASTI/MANGO	Registration No.	: MNAC/ENG/0002/2017			

Site Visit Checklist						
#	Description	As On Site	Objection	Remark		
1.	Approach Road					
2.	Whether Existing at Site	Yes				
3.	Whether connected with an existing public road	Yes				
4.	Status of road	Public				
5.	Nature of Road	Concrete				
6.	Width of approach road	6.3 mtrs				
7.	Whether road side drain exists	Yes				
8.	if Whether road side drain exists is Yes - Width	.45 mtrs				
9.	if Whether road side drain exists is Yes - Nature	Concrete				
10.	if Whether road side drain exists is Yes - Whether connected to	Public Drain				
11.	Site Situation					
12.	Whether the site is at road junction	No				
13.	Level of site in relation to approach road	.15 mtrs plus				
14.	Whether the area is subject to	Low lying land				
15.	Whether the locality is	Developing				
16.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	Shiv mandir 50 mtrs away				
17.	The vertical and horizontal distance from 33 KV/11 KV electric line	V-10 mtrs, H - 3 mtrs				
18.	Site Details					
19.	Whether the Site is vacant	Yes				
20.	Plot size (As per measurement)(In Sqmt)	802.51				
21.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No				
22.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	Attached				
23.	Any other information.	Provided				
24.	Verification Details					
25.	Verified the Amins report with/without site inspection and found correct	Yes				
26.	If No, Reason	NA				
27.	Verified the cadastral map					
28.	Land Use	Residential				
29.	Existing off site Physical Infrastructure:					
30.	Road	Yes				
31.	Sewerage	No				

32.	Drainage	No
33.	Water facility	No
34.	Availability of drain	Yes
35.	Telephone	Yes
36.	Electricity	Yes
37.	Risk Parameter	
38.	Dealing with inflammable/chemical	No
39.	Occupancy	Yes
40.	Site Surrounded by (physical features)	
41.	EAST	Others plot
42.	WEST	Others plot
43.	NORTH	Road
44.	SOUTH	Others plot
45.	Length of the Road(In Mtr.)	Exceeding 600 meter and upto 1000 meter
46.	Existing Width of the Road(In Mtr.)	6.3
47.	Proposed Width of the Road as per Master Plan(In Mtr.)	6.3
48.	Width of the RoadWidening(In Mtr.)	0.001

Site Visit Photographs :







Recommendation : Verified & found Ok Remark : Site inspection done and report submitted.

> Gajendar Kumar Junior Engg