## Mango NAC

## SITE VISIT REPORT

Proposal Details				
: SABRA KHATOON	Site Visit Date	: 28 October, 2017		
: MOHAMMAD BELAL NASIR	File No.	: MNAC/BP/0017/W08/2017		
: W08	Case Type	: New		
: 1641	Plot No.	112		
: jawahar nagar	Registration No.	: MNAC/ENG/0007/2016		
	: MOHAMMAD BELAL NASIR : W08 : 1641	: MOHAMMAD BELAL NASIRFile No.: W08Case Type: 1641Plot No.		

Site Visit Checklist				
Description	As On Site	Objection	Remark	
Approach Road				
Whether Existing at Site	Yes			
Whether connected with an existing public road	Yes			
Status of road	Public			
Nature of Road	Kutchha			
Width of approach road	4.40 M			
Whether road side drain exists	No			
if Whether road side drain exists is No - Distance from nearest drain	150 M			
if Whether road side drain exists is No - easibility to connect	Yes			
if Whether road side drain exists is No - Scope of widening of road	No			
Site Situation				
Whether the site is at road junction	No			
Level of site in relation to approach road	-0.150 M			
Whether the area is subject to	Low lying land			
Whether the locality is	Developing			
Distance of the plot from the nearest temple/ monument / Airport/ Other important building	500 M (Mahal Inn Hotel )			
The vertical and horizontal distance from 33 KV/11 KV electric line	H :- 2.25 M , V; -6.10M			
Site Details				
Whether the Site is vacant	Yes			
Plot size (As per measurement)(In Sqmt)	134.26			
Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No			
Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	Yes			
Any other information.	No.			
Verification Details				
Verified the Amins report with/without site inspection and found correct	No			
If No, Reason	No amin has been posted at MNAC			
Verified the cadastral map				
Land Use	Residential			
Existing off site Physical Infrastructure:				
Road	Yes			
	DescriptionApproach RoadWhether Existing at SiteWhether connected with an existing public roadStatus of roadNature of RoadWidth of approach roadWhether road side drain existsif Whether road side drain exists is No - Distance from nearest drainif Whether road side drain exists is No - easibility to connectif Whether road side drain exists is No - Scope of widening of roadSite SituationWhether the site is at road junctionLevel of site in relation to approach roadWhether the area is subject toWhether the locality isDistance of the plot from the nearest temple/ monument / Airport/ Other important buildingThe vertical and horizontal distance from 33 KV/11 KV electric lineSite DetailsWhether the applicant encroached the Govt. land/road land/ariange channelSketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageAny other information.Verified the Amins report with/without site inspection and found correctIf No, ReasonVerified the cadastral map Land UseExisting off site Physical Infrastructure:	DescriptionAs On SiteApproach RoadYesWhether Existing at SiteYesWhether connected with an existing public roadYesStatus of roadPublicNature of RoadKutchhaWidth of approach road4.40 MWhether road side drain existsNoif Whether road side drain exists is No - Distance from nearest drain150 Mif Whether road side drain exists is No - easibility to connectYesif Whether road side drain exists is No - Scope of widening of roadNoSite SituationNoWhether the site is at road junctionNoLevel of site in relation to approach road-0.150 MWhether the area is subject toLow lying landWhether the locality isDevelopingDistance of the plot from the nearest temple/ monument / Airport/ Other important buildingH :- 2.25 M , V; -6.10MSite DetailsYesWhether the applicant encroached the Govt. land/road land/any other land/drainage channelNoSketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYesAny other information.No.Verified the Amins report with/without site inspection and found correctNo amin has been posted at MNACIf No, ReasonNo amin has been posted at MNACNoNoVerified the cadastral mapLand UseResidential	DescriptionAs On SiteObjectionApproach RoadYesWhether Existing at SiteYesWhether connected with an existing public roadYesStatus of roadPublicNature of RoadKutchhaWidth of approach road4.40 MWhether road side drain existsNoIf Whether road side drain exists is No - Distance from nearest drain150 MIf Whether road side drain exists is No - Cope of widening of roadNoSite SituationYesWhether the site is at road junctionNoLevel of site in relation to approach road-0.150 MWhether the area is subject toLow lying landWhether the site is at road junctionNoWhether the loality isDevelopingDistance of the plot from the nearest temple/ monument / Airport/ Other important buildingHotel )The vertical and horizontal distance from 33 KV/11 KV electric lineYesSite DetailsYes </td	

31.	Sewerage	No
32.	Drainage	No
33.	Water facility	Yes
34.	Availability of drain	No
35.	Telephone	No
36.	Electricity	No
37.	Risk Parameter	
38.	Dealing with inflammable/chemical	No
39.	Occupancy	No
40.	Site Surrounded by (physical features)	
41.	EAST	Others Plot
42.	WEST	Others Plot
43.	NORTH	Road
44.	SOUTH	Others Plot
45.	Length of the Road(In Mtr.)	Exceeding 100 meter and upto 250 meter
46.	Existing Width of the Road(In Mtr.)	4.4
47.	Proposed Width of the Road as per Master Plan(In Mtr.)	4.4
48.	Width of the RoadWidening(In Mtr.)	0

## Site Visit Photographs :













Recommendation : Verified & found Ok Remark : ok

Gajendar Kumar Junior Engg