Mango NAC

Г

SITE VISIT REPORT

Proposal Details					
Owner Name	: sunil kumar	Site Visit Date	: 10 April, 2018		
Applicant Name	: GAURI SHANKAR SAHU	File No.	: MNAC/BP/0009/W09/2018		
Ward No.	: W09	Case Type	: New		
Thana No.	: 1641	Plot No.	1061		
Road No. / Name	:	Registration No.	: MNAC/ENG/0025/2017		

	Site Visit Checklist					
#	Description	As On Site	Objection	Remark		
1.	Approach Road					
2.	Whether Existing at Site	Yes				
3.	Whether connected with an existing public road	Yes				
4.	Status of road	Public				
5.	Nature of Road	Concrete				
6.	Width of approach road	7.30M				
7.	Whether road side drain exists	Yes				
8.	if Whether road side drain exists is Yes - Width	0.30M				
9.	if Whether road side drain exists is Yes - Nature	Concrete				
10.	if Whether road side drain exists is Yes - Whether connected to	Public Drain				
11.	Site Situation					
12.	Whether the site is at road junction	Yes				
13.	Level of site in relation to approach road	_0.10M				
14.	Whether the area is subject to	Low lying land				
15.	Whether the locality is	Developing				
16.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	450M Water Tank				
17.	The vertical and horizontal distance from 33 KV/11 KV electric line	No				
18.	Site Details					
19.	Whether the Site is vacant	Yes				
20.	Plot size (As per measurement)(In Sqmt)	251				
21.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No				
22.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	No				
23.	Any other information.	No				
24.	Verification Details					
25.	Verified the Amins report with/without site inspection and found correct	No				
26.	If No, Reason	No Amins posted in MNAC				
27.	Verified the cadastral map					
28.	Land Use	Residential				
29.	Existing off site Physical Infrastructure:					
30.	Road	Yes				

31.	Sewerage	No
32.	Drainage	Yes
	Water facility	Yes
34.	Availability of drain	Yes
35.	Telephone	No
36.	Electricity	Yes
37.	Risk Parameter	
38.	Dealing with inflammable/chemical	No
39.	Occupancy	No
40.	Site Surrounded by (physical features)	
41.	EAST	Other Plot
42.	WEST	Other Plot
43.	NORTH	Road
44.	SOUTH	Road
45.	Length of the Road(In Mtr.)	Exceeding 50 meter and upto 100 meter
46.	Existing Width of the Road(In Mtr.)	7.3
47.	Proposed Width of the Road as per Master Plan(In Mtr.)	7.3
48.	Width of the RoadWidening(In Mtr.)	0

Site Visit Photographs :









Recommendation : Verified & found Ok Remark : No

> Sukhram Munda Junior Engg