## **Mango Municipal Corporation**

## SITE VISIT REPORT

Proposal Details						
Owner Name	: SWAMI VIVEKANAND SEVA TRUST C/O	Site Visit Date	: 07 December, 2021			
Applicant Name	: SUMANARIYASICKA	File No.	: MNAC/BP/0016/W8/2019/ALT1			
Ward No.	: W8	Case Type	: Addition Alteration			
Thana No.	: 1641	Plot No.	3590,3591,3594,3595,3593,3596,			
Road No. / Name	: JESU BHAWAN(Pardih)	Registration No.	. 3597, 3598, 3509, 3600/P,3601, 3602/P,3603,3604/P,3600/PART, 3607,3608/PART			
Site Visit Checklist						

	Site Visit Checklist						
#	Description	As On Site	Objection	Remark			
1.	Whether Existing at Site	Yes					
2.	Whether connected with an existing public road	Yes					
3.	Status of road	Public					
4.	Nature of Road	Concrete					
5.	Width of approach road	8.23m					
6.	Whether road side drain exists	Yes					
7.	if Whether road side drain exists is Yes - Width	0.60m					
8.	if Whether road side drain exists is Yes - Nature	Concrete					
9.	if Whether road side drain exists is Yes - Whether connected to	Public Drain					
10.	Whether the site is at road junction	No					
11.	Level of site in relation to approach road	-0.10m					
12.	Whether the area is subject to	Low lying land					
13.	Whether the locality is	Developing					
14.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	15m Community College					
15.	The vertical and horizontal distance from 33 KV/11 KV electric line	10/25					
16.	Whether the Site is vacant	No					
17.	if Whether the Site is vacant No - Stage of construction	2					
18.	if Whether the Site is vacant No - No of Storey	2					
19.	if Whether the Site is vacant No - Nature of construction	RCC					
20.	if Whether the Site is vacant No - Sketch enclosed at page	Yes					
21.	Plot size (As per measurement)(In Sqmt)	22300					
22.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No					
23.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	Yes					
24.	Any other information.	No					
25.	Verified the Amins report with/without site inspection and found correct	No					
26.	If No, Reason	Not Amin Posted In MMC.					
27.	Land Use	Public semi Public					
28.	Road	Yes					
29.	Sewerage	No					
30.	Drainage	Yes					
	1	L	I				

31.	Water facility	Yes
32.	Availability of drain	Yes
33.	Telephone	No
34.	Electricity	Yes
35.	Dealing with inflammable/chemical	No
36.	Occupancy	No
37.	EAST	Road
38.	WEST	Other Plot
39.	NORTH	Other Plot
40.	SOUTH	Other Plot
41.	Length of the Road(In Mtr.)	Up to 50 meter
42.	Existing Width of the Road(In Mtr.)	8.23
43.	Proposed Width of the Road as per Master Plan(In Mtr.)	8.23
44.	Width of the RoadWidening(In Mtr.)	1
45.	Plot area (As per deed)	1

## Site Visit Photographs :





Recommendation : Having Objections & require to raise shortfall Remark : no

Santosh Kumar Town Planning Officer