

# Form IV

CSS No: 13  
Issue Date of CSS: 29/10/2020

## Certificate for Structure Stability (CSS)

(This certificate Adheres to Jharkhand Municipal Act 2011, Jharkhand Regional Development Authority Act 2002, Mineral Area Development Authority Act, Jharkhand Industrial Area Development Authority Act, & Jharkhand Building Bye Laws 2016)

Owner / Builder Name	: Mrs. Kalawati Devi	Village Name / Mouza Name	: Mango
Name of Local body	: Mango Nagar nigam	Project / Proposal Type	: Residential
Plot No.	: 2030, 2031	Occupancy Type/Purpose	: Residential
Ward No.	: 09	Supervision Certificate (SC) (No)	: 13
Thana name / No.	: Mango/1642	Issue date of Supervision Certificate	: 29/10/2020
Street address	: Rd No.05, Rudrubasa	Application / file no.	: MNAE/TEMP/BP/0080/w-09/20
Landmark / Locality	: Honda Service centre	Date and Time of Application / file	: 29/10/2020/ 8.15 PM.
Khasra/ Khatian No.	: 712	Name of Associated Technical Person (if any)	: Chandrika sharma

With respect to the building work for above said project/proposal type with respect of above referred plot, I certify that the structural calculations, plans and details including the relevant specifications of the building prepared by me, satisfy the structural safety requirements for all situations including natural disasters like cyclone & earth quake etc: as applicable under the Byelaws and stipulated under Part-6 (Structural Design) of the National Building Code of India, 2005 and other relevant codes; and the information given in this is factually correct to the best of my knowledge.

I undertake the responsibility with regard to supervision of the work at each and every stage of construction of the structure, regularly to the effect that the building is being constructed conforming to the structural plan prepared structural calculations, plans and details including the relevant specifications of the building prepared by me.

I will be responsible and liable for action by (Name of ULB ) Govt of Jharkhand if the plan/ design contain misrepresentation or fraudulent information and the construction is made in deviation from structural calculations, plans and details including the relevant specifications of the building prepared by me or if there is any structural failure due wrong /unsafe structural design/ use of low quality material and/ or poor workmanship endangering the safety of inmates or public and the structural stability of the building.

Authorized Signatory

(Name of Structure Engineer / Civil Engineer)

Registration No. MNAE/DE/TMIN/0017/2017

Validity No. 02/10/2020

Address: Gitanjali Complex, Dimna Rd, Mango, JSR.

Authorized Signatory

(Name of Owner/Builder)

Registration No. ....

Validity No. ....

Address: Road No.05, Rudrubasa, Mango