Mango Municipal Corporation

SITE VISIT REPORT

Proposal Details

Owner Name : SMT SATNAM KAUR Site Visit Date : 06 November, 2020

Applicant Name : Anoop Kumar File No. : MNAC/BP/0041/W09/2020

Ward No.: W09Case Type: NewThana No.: 1642Plot No.2096

Road No. / Name : SANKOSAI ROAD NO- 4, NEAR LAKI STEEL Registration No. : MNAC/ENG/0006/2016

DIMNA ROAD MANGO

| | Site Visit Checklist | | | | |
|-----|--|---------------------------------|-----------|--------|--|
| # | Description | As On Site | Objection | Remark | |
| | Whether Existing at Site | Yes | Objection | Kemark | |
| | Whether connected with an existing public road | Yes | | | |
| _ | Status of road | Public | | | |
| | Nature of Road | Blacktop | | | |
| | Width of approach road | 20m | | | |
| | Whether road side drain exists | Yes | | | |
| | if Whether road side drain exists is Yes - Width | 0.30m | | | |
| | if Whether road side drain exists is Yes - Width | Concrete | | | |
| | if Whether road side drain exists is Yes - Whether connected to | Public Drain | | | |
| 10. | Whether the site is at road junction | No | | | |
| 11. | Level of site in relation to approach road | -0.10m | | | |
| 12. | Whether the area is subject to | Low lying land | | | |
| 13. | Whether the locality is | Developing | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | 300m/ Ulidih Police Station. | | | |
| | The vertical and horizontal distance from 33 KV/11 KV electric line | 10/25 | | | |
| 16. | Whether the Site is vacant | Yes | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 323.29 | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | |
| | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | Yes | | | |
| 20. | Any other information. | No | | | |
| | Verified the Amins report with/without site inspection and found correct | No | | | |
| 22. | If No, Reason | No Amin Posted In MMC. | | | |
| 23. | Land Use | Residential | | | |
| 24. | Road | Yes | | | |
| 25. | Sewerage | No | | | |
| 26. | Drainage | Yes | | | |
| 27. | Water facility | Yes | | | |
| 28. | Availability of drain | Yes | | | |
| 29. | Telephone | No | | | |
| 30. | Electricity | Yes | | | |

Page 1 of 3 Printed on: 06 November, 2020

| 31. | Dealing with inflammable/chemical | No |
|-----|--|----------------|
| 32. | Occupancy | No |
| 33. | EAST | Road |
| 34. | WEST | Other Polt |
| 35. | NORTH | Other Plot |
| 36. | SOUTH | Other Plot |
| 37. | Length of the Road(In Mtr.) | Up to 50 meter |
| 38. | Existing Width of the Road(In Mtr.) | 20 |
| 39. | Proposed Width of the Road as per Master Plan(In Mtr.) | 20 |
| 40. | Width of the RoadWidening(In Mtr.) | 0 |
| 41. | Plot area (As per deed) | 0 |

Site Visit Photographs:







Page 2 of 3 Printed on: 06 November, 2020





Recommendation: Verified & found Ok

Remark : Site Inspection done & report submitted.

Subodh Kumar Das Junior Engg

Page 3 of 3 Printed on: 06 November, 2020