

Certificate for Structure Stability (CSS)

(This certificate Adheres to Jharkhand act-2011, Jharkhand Regional Development Authority Act-2002, Mineral Area Development Authority Act, Jharkhand Industrial Area Development Authority Act, & Jharkhand Building Bye-Laws 2016)

Owner/Builder Name	: Mrs. Shrikanti Devi w/o Mr. Vijay Kr. Singh	Village Name / Mouza Name	: Mangro
Name of Local body	: Mangro Nagar Nigam	Project / Proposal Type	: Residential
Plot No.	: 3887	Occupancy Type/Purpose	: Residential
Ward No.	: 10	Supervision certificate (SC) (No)	: 25
Thana Name / No.	: Mangro	Issue Date of Supervision Certificate	: 10/04/2021
Street address	: Baleshwar Path Dimma Rd, Mangro	Application / file no.	: HNRCLTE/MP/8P/0037/W10/2021
Landmark/Locality	: SBI Bank.	Date and Time of Application/file	: 10/04/2021/9.50PM.
Khasra/Khatian No.	: 36	Name of Associated Technical Person (if any)	: Chandrika Sharma

With respect to the building work for above said project/proposal type with respect of above referred plot, I certify that the structural calculations, plans and details including the relevant specifications of the building prepared by me, satisfy the structural safety requirements for all situations including natural disasters like cyclone & earth quake etc: as applicable under the byelaws and stipulated under part-6 (Structural Design) of the National Building Code of India, 2005 and other relevant codes; and the information given in this is factually correct to the best of my knowledge.

I undertake the responsibility with regard to supervision of the work at each and every stage of construction of the structure, regularly to the effect that the building is being constructed conforming to the structural plan prepared structural calculations, plans and details including the relevant specifications of the building prepared by me.

I will be responsible and liable for action by (Name of ULB) Govt. of Jharkhand if the plan/design contain misrepresentation or fraudulent information and the construction is made in deviation from structural calculations, plans and details including the relevant specifications of the building prepared by me or if there is any structural failure due wrong/unsafe structural design/ use of low quality material and/ or poor workmanship endangering the safety of inmates or public and the structural stability of the building.

Authorized Signatory



(Name of structure engineer/Civil Engineer)

Registration No. MNRCLTE/MP/0017/2017

Validity No. 11/02/2022

Address: Sri. Tanjali Madhusudan Complex

Dimna Rd, Mangro, JSR.

Authorized Signatory



(Name of owner/builder)

Registration no.

Validity No.

Address: