Form - IV

CSS No		• •	• •	•	• •	••	•
Issue Date of CSS	••						

Certificate for Structure Stability (CSS)

(This Certificate Adheres to Jharkhand Municipal Act 2011, Jharkhand Regional Development Authority Act 2002, Mineral Area Development Authority Act, Jharkhand Building Bye - Laws 2016)

Owner/ Builder Name : INSTITUTE OF THE SISTER OF Village Name / Mouza Name : MANGO

CHARITY OF JESUS & MARY

Name of Local body : MNAC Project/ Proposal Type : RESIDENTIAL

New Plot No. : 2258, 2259, 2272, 2273, 2274 Occupancy Type/Purpose : DORMITORY

Ward No. : 9 Supervision Certificate (SC) (NO) :

Thana name/No. : 1642 Issue date of Supervision Certificate :

Street address : ROAD NO - 5, SANKOSAI, GODROBASA, MANGO

Application/file no. : MNAC/TEMP/BP/0070/W09/2021

Landmark/Locality: NEAR TIRKEY PLAYGROUND, ROAD NO - 5,

SANKOSAI, MANGO Date and Time of Application/file : 30/08/2021

Khata No. : 183, 908 Name of Associated Technical Person(if any) : LAWRENCE FRANCIS

With respect to the building work for above said project/proposal type with respect of above refereed plot, I certify that the structural calculations, plans and details including the relevant specifications of the building prepared by me, satisfy the structural safety requirements for situations including natural disasters like cyclone & earth quake etc: as applicable under the Byelaws and stipulated under part-6 (structural design) of the national building code of India, 2005 and other relevant codes, and the information given in this is factually corrected to the best of my knowledge.

I Undertake the responsibility with regard to supervision of the work at each and every stage of construction of the structure, regularly to the effect that the building is being constructed con forming to the structure plan prepared structural calculations, plan and details including the relevant specifications of the building prepared by me.

I will be responsible and liable for action by (Name of ULB) Govt of Jharkhand if the plan/design contain misrepresentation or fraudulent information and the construction is made in deviation from structural calculations, plans and details including the relevant specifications of the building prepared by me or if there is any structural failure due wrong/unsafe structural design/ use of low quality material and/or poor workmanship endangering the safety of inmates or public and the structural stability of the building.

Rentu Ranjan Oskael
Authorized Signatory

(Name of Structure Engineer/civil Engineer)

Registration No......Validity No.....

Address

Authorized Signatory (Name of Owner/Builder)

L. Rashmi

Registration No.....

Validity No...... Address