CSS	No:		=		-			
Issue	Date of CSS		,	•				

Form IV Certificate for Structure Stability (CSS)

(This certificate Adheres to Jharkhand Municipal Act 2011, Jharkhand Regional Development Authority Act 2002, Mineral Area Development Authority Act, Jharkhand Industrial Area Development Authority Act, & Jharkhand Building Bye Laws 2016)

Village Name / Mouza Name Owner / Builder Name :SMT. ANITA SINGH Project / Proposal Type Name of Local body :MNAC Occupancy Type/Purpose :1541 Plot No. Supervision Certificate (SC) (No) :09 Ward No. Issue date of Supervision Certificate Thena name / No. :1641 Application / file no. Street address :Near Sunshine Complex, Arpit Road, Mango Landmark / Locality

:Sunshine Complex, Arpit Road, Mango

Khasra/ Khatian No.

Date and Time of Application / file

Name of Associated Technical Person (if any) :

: MANGO : RESIDENTIAL

:personal residence

:18.07.21

:MNAC/TEMP/BP/0058/W09/2021

:18.07.21

With respect to the building work for above said project/proposal type with respect of above referred plot, I certify that the structural calculations, plans and details including the relevant specifications of the building prepared by me, satisfy the structural safety requirements for all situations including natural disasters like cyclone & earth quake etc: as applicable under the Byelaws and stipulated under Part-6 (Structural Design) of the National Building Code of India, 2005 and other relevant codes; and the information given in this is factually correct to the best of my knowledge.

I undertake the responsibility with regard to supervision of the work at each and every stage of construction of the structure, regularly to the effect that the building is being constructed conforming to the structural plan prepared structural calculations, plans and details including the relevant specifications of the building prepared by me.

I will be responsible and liable for action by (MNAC) Govt of Jharkhand if the plan/ design contain misrepresentation or fraudulent information and the construction is made in deviation from structural calculations, plans and details including the relevant specifications of the building prepared by me or if there is any structural failure due wrong /unsafe structural design/ use of low quality material and/ or poor workmanship endangering the safety of inmates or public and the structural stability of the building. COTTON ESE

DIMPLE JAIN Jain
Authoritist RC / 0004 / 2015 (Name of Structure Engineer / Civil Engineer)

Registration No

Validity No..... Address:....

:292

Authorized Signatory

(Name of Owner/Builder)

Registration No..... Validity No.....

Address:....