

Certificate for Structure Stability (CSS)

CSS No:
Issue Date of CSS: 02/09/21.


(This certificate Adheres to Jharkhand Municipal Act 2011, Jharkhand Regional Development Authority Act 2002, Mineral Area Development Authority Act, Jharkhand Industrial Area Development Authority Act, & Jharkhand Building Bye Laws 2016)


Owner / Builder Name	: Mr. Janki Ram	Village Name / Mouza Name	: Mangra
Name of Local body	: Mangra Nagar Wigan	Project / Proposal Type	: Residential
Plot No.	: 4802	Occupancy Type/Purpose	: Residential
Ward No.	: 09	Supervision Certificate (SC) (No)	: 28
Thana name / No.	: Mangra/642	Issue date of Supervision Certificate	: 02/09/2021
Street address	: Panchendra Nagar, Mangra	Application / File no.	: MNAC/TEM/158/0072/10-09/21
Landmark / Locality	: Salgachh Maidan	Date and Time of Application / File	: 02/09/2021/10.00 AM
Khasra/ Khata No.	: 694	Name of Associated Technical Person (if any)	: Chandriks Sharma

With respect to the building work for above said project/proposal type with respect of above referred plot, I certify that the structural calculations, plans and details including the relevant specifications of the building prepared by me, satisfy the structural safety requirements for all situations including natural disasters like cyclone & earth quake etc: as applicable under the Byelaws and stipulated under Part-6 (Structural Design) of the National Building Code of India, 2005 and other relevant codes; and the information given in this is factually correct to the best of my knowledge.

I undertake the responsibility with regard to supervision of the work at each and every stage of construction of the structure, regularly to the effect that the building is being constructed conforming to the structural plan prepared structural calculations, plans and details including the relevant specifications of the building prepared by me.

I will be responsible and liable for action by (Name of ULB) Govt of Jharkhand if the plan/ design contain misrepresentation or fraudulent information and the construction is made in deviation from structural calculations, plans and details including the relevant specifications of the building prepared by me or if there is any structural failure due wrong /unsafe structural design/ use of low quality material and/ or poor workmanship endangering the safety of inmates or public and the structural stability of the building.

Authorized Signatory  Chandriks Sharma.
(Name of Structure Engineer / Civil Engineer)
Registration No. MNAC/ITEM/158/0072/10-09/21
Validity No. 11/02/2022
Address: Gaitangachi Complex, Dimna Rd, Mangra

Authorized Signatory 
(Name of Owner/Builder)
Registration No.
Validity No.
Address: