Mango Municipal Corporation

SITE VISIT REPORT

Proposal Details

Owner Name : 1. SHAMIM AHMAD SHAMIM S/O- Site Visit Date : 28 July, 2023

Applicant Name : MOHAMMAD ISMAIL HUSSAIN 2. MRS. File No. : MNAC/BP/0043/W08/2023

Ward No. : AND SHAMIM Case Type : New Thana No. : 1641 Plot No. 3600

Road No. / Name : RABBANI COLONY, NR-KARIM CITY Registration No. : MNAC/DFTMN/0008/2020

COLLEGE, MANGO, JAMSHEDPUR

| | Site Visit Checklist | | | | |
|-----|--|--|-----------|--------|--|
| # | Description | As On Site | Objection | Remark | |
| 1. | Whether Existing at Site | Yes | | | |
| 2. | Whether connected with an existing public road | Yes | | | |
| 3. | Status of road | Public | | | |
| 4. | Nature of Road | Concrete | | | |
| 5. | Width of approach road | 4.87m | | | |
| 6. | Whether road side drain exists | Yes | | | |
| 7. | if Whether road side drain exists is Yes - Width | 0.30m | | | |
| 8. | if Whether road side drain exists is Yes - Nature | Concrete | | | |
| 9. | if Whether road side drain exists is Yes - Whether connected to | Public Drain | | | |
| 10. | Whether the site is at road junction | No | | | |
| 11. | Level of site in relation to approach road | -0.10m | | | |
| 12. | Whether the area is subject to | Low lying land | | | |
| 13. | Whether the locality is | Developing | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | Karim City College Road | | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | 11/25 | | | |
| 16. | Whether the Site is vacant | Yes | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 165.82 | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | Yes | | | |
| 20. | Any other information. | No | | | |
| 21. | Verified the Amins report with/without site inspection and found correct | No | | | |
| 22. | If No, Reason | Land verification as per co mango report | | | |
| 23. | Land Use | Residential | | | |
| 24. | Road | Yes | | | |
| 25. | Sewerage | No | | | |
| 26. | Drainage | Yes | | | |
| 27. | Water facility | Yes | | | |
| 28. | Availability of drain | Yes | | | |
| 29. | Telephone | Yes | | | |
| 30. | Electricity | Yes | | | |

Page 1 of 3 Printed on: 28 July, 2023

| 31. | Dealing with inflammable/chemical | No |
|-----|--|----------------|
| 32. | Occupancy | No |
| 33. | EAST | photo attached |
| 34. | WEST | photo attached |
| 35. | NORTH | photo attached |
| 36. | SOUTH | photo attached |
| 37. | Length of the Road(In Mtr.) | Up to 50 meter |
| 38. | Existing Width of the Road(In Mtr.) | 4.87 |
| 39. | Proposed Width of the Road as per Master Plan(In Mtr.) | 4.87 |
| 40. | Width of the RoadWidening(In Mtr.) | 0 |
| 41. | Plot area (As per deed) | 0 |

Site Visit Photographs:







Page 2 of 3 Printed on: 28 July, 2023





 $\textbf{Recommendation} \ : \ Verified \ \& \ found \ Ok$

Remark : OK

Subodh Kumar Junior Engg

Page 3 of 3 Printed on: 28 July, 2023