Chaibasa Nagar Parshad

SITE VISIT REPORT

Proposal Details

Owner Name : SMT. SABITA PANJA AND SRI SAMIT KR. Site Visit Date : 04 December, 2018

Applicant Name : RONAL GUIN File No. : CNP/BP/0006/W18/2018

Ward No. : W18 Case Type : New

Thana No. : 644 Plot No. 2046(OLD) & 134 A&C(NEW)

Road No. / Name : AMLA TOLA Registration No. : CNP/ENG/0006/2017

Site Visit Checklist						
#	Description	As On Site	Objection	Remark		
1.	Whether Existing at Site	No		APPROVED		
2.	Whether connected with an existing public road	Yes		APPROVED		
3.	Status of road	Public		APPROVED		
4.	Nature of Road	Blacktop		APPROVED		
5.	Width of approach road	4.87 metre		APPROVED		
6.	Whether road side drain exists	No		APPROVED		
7.	if Whether road side drain exists is Yes - Width	0.61 M		APPROVED		
8.	if Whether road side drain exists is Yes - Nature	Concrete		APPROVED		
9.	if Whether road side drain exists is Yes - Whether connected to	Public Drain		APPROVED		
10.	if Whether road side drain exists is No - Distance from nearest drain	200 meters				
	if Whether road side drain exists is No - easibility to connect	No				
12.	if Whether road side drain exists is No - Scope of widening of road	no				
13.	Whether the site is at road junction	No		APPROVED		
14.	Level of site in relation to approach road	down		APPROVED		
15.	Whether the area is subject to	Low lying land		APPROVED		
16.	Whether the locality is	Developing		APPROVED		
17.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	no		FOUND OK		
18.	The vertical and horizontal distance from 33 KV/11 KV electric line	no		FOUND OK		
19.	Whether the Site is vacant	Yes		FOUND OK		
20.	Plot size (As per measurement)(In Sqmt)	90.13		FOUND OK		
21.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No		APPROVED		
22.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	approval		APPROVED		
23.	Any other information.	approved		APPROVED		
24.	Verified the Amins report with/without site inspection and found correct	Yes		APPROVED		
25.	Land Use	Residential		APPROVED		
26.	Road	Yes		FOUND OK		
27.	Sewerage	Yes		FOUND OK		
28.	Drainage	Yes		FOUND OK		
29.	Water facility	Yes		FOUND OK		
30.	Availability of drain	Yes		FOUND OK		

Page 1 of 3 Printed on: 26 January, 2019

31.	Telephone	Yes	ОК
32.	Electricity	Yes	FOUND OK
33.	Dealing with inflammable/chemical	No	APPROVED
34.	Occupancy	No	APPROVED
35.	EAST	VINAY KRISHNA MITRA	FOUND OK
36.	WEST	PART OF PLOT 134	FOUND OK
37.	NORTH	ROAD	FOUND OK
38.	SOUTH	PART OF PLOT 134	FOUND OK
39.	Length of the Road(In Mtr.)	Exceeding 100 meter and upto 250 meter	APPROVED
40.	Existing Width of the Road(In Mtr.)	4.87	APPROVED
41.	Proposed Width of the Road as per Master Plan(In Mtr.)	4.87	APPROVED
42.	Width of the RoadWidening(In Mtr.)	4.87	APPROVED
43.	Plot area (As per deed)	90.13	

Site Visit Photographs:





Page 2 of 3 Printed on: 26 January, 2019







Recommendation: Verified & found Ok

 $\textbf{Remark} \hspace{0.1cm} : \hspace{0.1cm} ok \hspace{0.1cm}$

Rajesh Kumar Junior Engg

Page 3 of 3 Printed on: 26 January, 2019