Gumla Nagar Parishad

Г

SITE VISIT REPORT

Proposal Details						
Owner Name	: ANIL KUMAR AGARWAL	Site Visit Date	: 13 October, 2020			
Applicant Name	: DEEN DAYAL GUPTA	File No.	: GUNPC/BP/0040/W13/2020			
Ward No.	: W13	Case Type	: New			
Thana No.	: 59	Plot No.	502			
Road No. / Name	: dhobi muhalla ,gumla	Registration No.	: GUNPC/ENG/0002/2017			

Site Visit Checklist						
#	Description	As On Site	Objection	Remark		
1.	Whether Existing at Site	Yes		APPROVED		
2.	Whether connected with an existing public road	Yes		APPROVED		
3.	Status of road	Public		APPROVED		
4.	Nature of Road	Concrete		APPROVED		
5.	Width of approach road	4.26 M		UPLOAD		
6.	Whether road side drain exists	Yes		APPROVED		
7.	if Whether road side drain exists is Yes - Width	0.91 M		APPROVED		
8.	if Whether road side drain exists is Yes - Nature	Concrete		APPROVED		
-	if Whether road side drain exists is Yes - Whether connected to	Public Drain		APPROVED		
10.	Whether the site is at road junction	No		APPROVED		
11.	Level of site in relation to approach road	BELOW ROAD LEVEL		APPROVED		
12.	Whether the area is subject to	NA		APPROVED		
13.	Whether the locality is	Developing		APPROVED		
	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	NA		APPROVED		
	The vertical and horizontal distance from 33 KV/11 KV electric line	NA		APPROVED		
16.	Whether the Site is vacant	Yes		APPROVED		
17.	Plot size (As per measurement)(In Sqmt)	103.68		APPROVED		
	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	Yes		APPROVED		
	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	ATTACHED		APPROVED		
20.	Any other information.	NA		APPROVED		
	Verified the Amins report with/without site inspection and found correct	Yes		APPROVED		
22.	Land Use	Residential		APPROVED		
23.	Road	Yes		APPROVED		
24.	Sewerage	No		APPROVED		
25.	Drainage	Yes		APPROVED		
26.	Water facility	Yes		APPROVED		
27.	Availability of drain	Yes		APPROVED		
28.	Telephone	No		APPROVED		
29.	Electricity	Yes		APPROVED		
30.	Dealing with inflammable/chemical	No		APPROVED		

31.	Occupancy	No	APPROVED
32.	EAST	EAST	UPLOAD
33.	WEST	WEST	UPLOAD
34.	NORTH	NORTH	UPLOAD
35.	SOUTH	SOUTH	UPLOAD
36.	Length of the Road(In Mtr.)	Exceeding 50 meter and upto 100 meter	APPROVED
37.	Existing Width of the Road(In Mtr.)	4.26	APPROVED
38.	Proposed Width of the Road as per Master Plan(In Mtr.)	0	APPROVED
39.	Width of the RoadWidening(In Mtr.)	0.76	APPROVED
40.	Plot area (As per deed)	111.32	APPROVED

Site Visit Photographs :











Recommendation : Verified & found Ok Remark : OK

> Anjeeta Kauranya Lakra Junior Engg