Gumla Nagar Parishad

SITE VISIT REPORT

Proposal Details

Owner Name : GOPAL SHARMA Site Visit Date : 01 August, 2023

Applicant Name : RAWNIT KUMAR File No. : GUNPC/BP/0042/W17/2023

Ward No.: W17Case Type: NewThana No.: 59Plot No.890

Road No. / Name : Registration No. : GUNPC/ENG/0004/2019

| Site Visit Checklist | | | | | | | |
|----------------------|--|--------------------------------|-----------|----------|--|--|--|
| # | Description | As On Site | Objection | Remark | | | |
| 1. | Whether Existing at Site | Yes | | | | | |
| 2. | Whether connected with an existing public road | Yes | | | | | |
| 3. | Status of road | Public | | | | | |
| 4. | Nature of Road | Kutchha | | | | | |
| 5. | Width of approach road | 4.57 | | UPLOADED | | | |
| 6. | Whether road side drain exists | No | | | | | |
| 7. | if Whether road side drain exists is No - Distance from nearest drain | 20M | | | | | |
| | if Whether road side drain exists is No - easibility to connect | Yes | | | | | |
| 9. | if Whether road side drain exists is No - Scope of widening of road | 0.91M | | | | | |
| 10. | Whether the site is at road junction | Yes | | | | | |
| 11. | Level of site in relation to approach road | ABOVE 1 FT ROAD LEVEL | | | | | |
| 12. | Whether the area is subject to | NA | | | | | |
| 13. | Whether the locality is | Developing | | | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | 300 MTR MURLI BAGICHA TALAB | | | | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | NA | | | | | |
| 16. | Whether the Site is vacant | Yes | | | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 141.68 | | | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | ATTACHED | | | | | |
| 20. | Any other information. | NA | | | | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | | | | |
| 22. | Land Use | Residential | | | | | |
| 23. | Road | Yes | | | | | |
| 24. | Sewerage | No | | | | | |
| 25. | Drainage | Yes | | | | | |
| 26. | Water facility | Yes | | | | | |
| 27. | Availability of drain | Yes | | | | | |
| 28. | Telephone | No | | | | | |
| 29. | Electricity | Yes | | | | | |
| 30. | Dealing with inflammable/chemical | No | | | | | |

Page 1 of 3 Printed on: 31 July, 2023

| 31. | Occupancy | No | | |
|-----|--|---------------------------------------|---|----------|
| 32. | EAST | EAST | | UPLOADED |
| 33. | WEST | WEST | | UPLOADED |
| 34. | NORTH | NORTH | | UPLOADED |
| 35. | SOUTH | SOUTH | | UPLOADED |
| 36. | Length of the Road(In Mtr.) | Exceeding 50 meter and upto 100 meter | | |
| 37. | Existing Width of the Road(In Mtr.) | 4.57 | | |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 5.1 | | |
| 39. | Width of the RoadWidening(In Mtr.) | 0 | _ | _ |
| 40. | Plot area (As per deed) | 141.68 | | |

Site Visit Photographs:







Page 2 of 3 Printed on: 31 July, 2023





Recommendation: Verified & found Ok
Remark: SITE IS VACANT AND VISITED

Anand Kumar Murmu Junior Engg

Page 3 of 3 Printed on: 31 July, 2023