Form IV

CSS NO: TNE | CSS | 19117 Issue Date of CSS : 12 1217-

Certificate for Structure Stability (CSS)

(This certificate Adheres to Jharkhand Municipal Act 2011, Jharkhand Regional Development Authority Act 2002, Mineral Area Development Authority Act, Jharkhand Industrial Area Development Authority Act, & Jharkhand Building Bye Lews 2016)

	a. O. I diam stada	Village Name / Mouza Name	: Telai	19
Owner / Builder Name	: Sri Baleshwer yadas Nillage Name / Mouza Name Sto Li Ramal yada u Thurmi Telai 19 Niegar Pan Bh		: Grene	ral
Name of Local body				
Plot No.	: 534G	Occupancy Type/Purpose	Reside	
Ward No.	÷ 02	Supervision Certificate (SC) (No)	INP	sc1 14/17
Thana name / No.	Telaiya (244)	Issue date of Supervision Certificate	12/10	F1/12
	16001.6213	Application / file no.	- JNP	114/17
Street address		Date and Time of Application / file		
Landmark / Locality		Name of Associated Technical Person (if any)		
Khasra/ Khatian No.	: 277	Name or resources a series		

With respect to the building work for above said project/proposal type with respect of above referred plot, I certify that the structural calculations, plans and details including the relevant specifications of the building prepared by me, satisfy the structural safety requirements for all situations including natural disasters like cyclone & earth quake etc: as applicable under the Byelaws and stipulated under Part-6 (Structural Design) of the National Building Code of India, 2005 and other relevant codes; and the information given in this is factually correct to the best of my knowledge.

I undertake the responsibility with regard to supervision of the work at each and every stage of construction of the structure, regularly to the effect that the building is being constructed conforming to the structural plan prepared structural calculations, plans and details including the relevant specifications of the building prepared by me.

I will be responsible and liable for action by (Name of ULB) Govt of Jharkhand if the plan/ design contain misrepresentation or fraudulent information and the construction is made in deviation from structural calculations, plans and details including the relevant specifications of the building prepared by me or if there is any structural failure due wrong /unsafe structural design/ use of low quality material and/ or poor workmanship endangering the safety of inmates or public and the structural stability of the building.

中では19で17のかりのでは15/41 いいいい カリ 35 まかり 日211日 CANT Engineer) (ENXIT 0001 117 21-1717月 Val

Registration No.JAIR LAKE 0001 17 Validity No. 2 3 0 3 118
Address: Gurso Micoru 4

Authorized Signatory

(Name of Owner/Builder)

Registration No... Validity No....

Address:....