Lohardaga Nagar Parishad

SITE VISIT REPORT

Proposal Details

Owner Name : SMT JAYANTI DEVI Site Visit Date : 20 March, 2018

Applicant Name : ASHWINI KUMAR SAHU File No. : LNP/BP/0004/W08/2018

 Ward No.
 : W08
 Case Type
 : New

 Thana No.
 : 194
 Plot No.
 27/1072

Road No. / Name : NEAR BABA MATH, LOHARDAGA Registration No. : LNP/ENG/0005/2017

Site Visit Checklist					
#	Description	As On Site	Objection	Remark	
1.	Approach Road				
2.	Whether Existing at Site	Yes			
3.	Whether connected with an existing public road	Yes			
4.	Status of road	Public			
5.	Nature of Road	Kutchha			
6.	Width of approach road	3.6 M			
7.	Whether road side drain exists	No			
8.	if Whether road side drain exists is No - Distance from nearest drain	80 M			
	if Whether road side drain exists is No - easibility to connect	Yes			
	if Whether road side drain exists is No - Scope of widening of road	Yes			
11.	Site Situation				
12.	Whether the site is at road junction	No			
13.	Level of site in relation to approach road	300 mm up			
14.	Whether the area is subject to	Low lying land			
15.	Whether the locality is	Developing			
16.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	Baba matha 15 M			
17.	The vertical and horizontal distance from 33 KV/11 KV electric line	12 M			
18.	Site Details				
19.	Whether the Site is vacant	No			
20.	if Whether the Site is vacant No - Stage of construction	1			
21.	if Whether the Site is vacant No - No of Storey	2			
22.	if Whether the Site is vacant No - Nature of construction	RCC			
23.	if Whether the Site is vacant No - Sketch enclosed at page	Yes			
24.	Plot size (As per measurement)(In Sqmt)	86.86			
25.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No			
26.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	Yes			
27.	Any other information.	No			
28.	Verification Details				
29.	Verified the Amins report with/without site inspection and found correct	Yes			
30.	Verified the cadastral map				

Page 1 of 3 Printed on: 03 April, 2018

31. Land Use Residential 32. Existing off site Physical Infrastructure: 33. Road Yes 34. Sewerage No 35. Drainage No 36. Water facility No 37. Availability of drain No 38. Telephone No 39. Electricity Yes 40. Risk Parameter 41. Dealing with inflammable/chemical No 42. Occupancy No 43. Site Surrounded by (physical features) 44. EAST Plot no 1073	
33. Road Yes 34. Sewerage No 35. Drainage No 36. Water facility No 37. Availability of drain No 38. Telephone No 39. Electricity Yes 40. Risk Parameter 41. Dealing with inflammable/chemical No 42. Occupancy No 43. Site Surrounded by (physical features) 44. EAST Plot no 1073	
34. Sewerage No 35. Drainage No 36. Water facility No 37. Availability of drain No 38. Telephone No 39. Electricity Yes 40. Risk Parameter 41. Dealing with inflammable/chemical No 42. Occupancy No 43. Site Surrounded by (physical features) 44. EAST Plot no 1073	
35. Drainage No No 36. Water facility No 37. Availability of drain No 38. Telephone No 40. Risk Parameter 41. Dealing with inflammable/chemical 42. Occupancy No 43. Site Surrounded by (physical features) 44. EAST No	
36. Water facility No No 37. Availability of drain No 38. Telephone No 39. Electricity Yes 40. Risk Parameter 41. Dealing with inflammable/chemical No 42. Occupancy No 43. Site Surrounded by (physical features) Plot no 1073	
37. Availability of drain 38. Telephone No 39. Electricity 40. Risk Parameter 41. Dealing with inflammable/chemical 42. Occupancy No 43. Site Surrounded by (physical features) 44. EAST No No Plot no 1073	
38. Telephone No Yes 40. Risk Parameter 41. Dealing with inflammable/chemical No 42. Occupancy No 43. Site Surrounded by (physical features) 44. EAST Plot no 1073	
39. Electricity 40. Risk Parameter 41. Dealing with inflammable/chemical 42. Occupancy 43. Site Surrounded by (physical features) 44. EAST No Plot no 1073	
40. Risk Parameter 41. Dealing with inflammable/chemical 42. Occupancy 43. Site Surrounded by (physical features) 44. EAST Plot no 1073	
41. Dealing with inflammable/chemical No 42. Occupancy No 43. Site Surrounded by (physical features) 44. EAST Plot no 1073	
42. Occupancy No 43. Site Surrounded by (physical features) 44. EAST Plot no 1073	
43. Site Surrounded by (physical features) 44. EAST Plot no 1073	
44. EAST Plot no 1073	
2.61	
45. WEST Plot no27/1072 rajesh mahto	
46. NORTH 12 feet wide road	
47. SOUTH Plot no 27/1072 rajesh mahto	
48. Length of the Road(In Mtr.) Exceeding 250 meter and upto 300 meter	
49. Existing Width of the Road(In Mtr.) 3.6	
50. Proposed Width of the Road as per Master Plan(In Mtr.) 3.6	
51. Width of the RoadWidening(In Mtr.) 3.6	

Site Visit Photographs:





Page 2 of 3 Printed on: 03 April, 2018







Recommendation : Remark :

Deepak Kumar Junior Engg

Page 3 of 3 Printed on: 03 April, 2018