Bundu Nagar Panchayat

SITE VISIT REPORT

Proposal Details

Owner Name : ABHIRAM MACHHUWA Site Visit Date : 19 July, 2017

Applicant Name : Arun Ranjan File No. : BNPC/BP/0003/W01/2017

Ward No. : W01 Case Type : New Thana No. : 28 Plot No. 2639

Road No. / Name : TUNJU Registration No. : BNPC/ARC/0002/2016

Site Visit Checklist							
#	Description	As On Site	Objection	Remark			
1.	Approach Road						
2.	Whether Existing at Site	Yes					
3.	Whether connected with an existing public road	Yes					
4.	Status of road	Public					
5.	Nature of Road	Kutchha					
6.	Width of approach road	3.048m					
7.	Whether road side drain exists	No					
8.	if Whether road side drain exists is No - Distance from nearest drain	50m					
9.	if Whether road side drain exists is No - easibility to connect	Yes					
10.	if Whether road side drain exists is No - Scope of widening of road	yes					
11.	Site Situation						
12.	Whether the site is at road junction	No					
13.	Level of site in relation to approach road	same level					
14.	Whether the area is subject to	Low lying land					
15.	Whether the locality is	Developing					
16.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	50m from behind kasturba gandhi girls high school,bundu					
17.	The vertical and horizontal distance from 33 KV/11 KV electric line	50m from 220 V electric pole					
18.	Site Details						
19.	Whether the Site is vacant	Yes					
20.	Plot size (As per measurement)(In Sqmt)	242.54					
21.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No					
22.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	430m from khudiya talab, bundu					
23.	Any other information.	No					
24.	Verification Details						
25.	Verified the Amins report with/without site inspection and found correct	Yes					
26.	If No, Reason	nothing					
27.	Verified the cadastral map						
28.	Land Use	Residential					
29.	Existing off site Physical Infrastructure:						

Page 1 of 3 Printed on: 07 October, 2017

30.		V	
30.	Road	Yes	
31.	Sewerage	No	
32.	Drainage	No	
33.	Water facility	No	
34.	Availability of drain	No	
35.	Telephone	No	
36.	Electricity	Yes	
37.	Risk Parameter		
38.	Dealing with inflammable/chemical	No	
39.	Occupancy	No	
40.	Site Surrounded by (physical features)		
41.	EAST	plot of golok bihari and others	
42.	WEST	plot of shyamsundar chel and others	
43.	NORTH	proposed road	
44.	SOUTH	plot of pavitra kumar and others	
45.	Length of the Road(In Mtr.)	Up to 50 meter	
46.	Existing Width of the Road(In Mtr.)	3.048	
47.	Proposed Width of the Road as per Master Plan(In Mtr.)	3.6	
48.	Width of the RoadWidening(In Mtr.)	0.3048	

Site Visit Photographs:





Page 2 of 3 Printed on: 07 October, 2017





Recommendation: Having Objections & require to raise shortfall

Remark :

Vineeta Kumari Junior Engg

Page 3 of 3 Printed on: 07 October, 2017