Simdega Nagar Panchayat

SITE VISIT REPORT

Proposal Details						
Owner Name	: NILMANI TOPPO	Site Visit Date	: 12 October, 2021			
Applicant Name	: MD RAGIB SAYEED	File No.	: SINPC/BP/0218/W02/2021			
Ward No.	: W02	Case Type	: New			
Thana No.	: 80	Plot No.	4916			
Road No. / Name	: THAKURTOLI SIMDEGA	Registration No.	: SINPC/ENG/0001/2017			

Industry of the order of the production of the producting production of		Site Visit Checklist				
2. Whether connected with an existing public road Yes 3. Status of road Public Image: Connected with an existing public road 4. Nature of Road Morum Image: Connected with an existing public road 5. Width of approach road 4.57 Image: Connected with an exists is No - Distance from noad side drain exists is No - easibility to connect 7. If Whether road side drain exists is No - easibility to connect Yes Image: Connect Connect 9. If Whether road side drain exists is No - Scope of widening of road N/A Image: Connect Connect 10. Whether the ads is a troad junction No Image: Connect Connect Connect Image: Connect Connect 11. Level of site in relation to approach road UP Image: Connect Connet Connec Connect Connect Connect Connect Connect Conn	#	Description	As On Site	Objection	Remark	
3. Status of road Public Image: Constraint of the state sta	1.	Whether Existing at Site	Yes			
4. Nature of Road Morum 5. Width of approach road 4.57 6. Whether road side drain exists No 7. If Whether road side drain exists is No - Distance from nearest drain N/A 8. If Whether road side drain exists is No - easibility to connect Yes 9. If Whether road side drain exists is No - Scope of widening of road N/A 10. Whether the site is a troad junction No 11. Level of site in relation to approach road UP 12. Whether the site is a troad junction No 13. Whether the locality is Developing 14. Distance of the plot from the nearest temple/ monument / Airport Other important building 1000 15. The vertical and horizontal distance from 33 KV/11 KV electric line 600 16. Whether the site is avaant Yes 17. Plot size (As per measurement)(In Sqmt) 793.39 18. Whether the applicant encroached the Govt. land/road land/any other land/rainage channel No 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page YES 20. Any other ind/ortand. N/A Image: Severage 21. Land Use Residential Image: Severage 22. Land Use Residential Image: Severage 23. Road Yes Image: Severage	2.	Whether connected with an existing public road	Yes			
Notion Notion 6 Whether road side drain exists No 7 If Whether road side drain exists is No - Distance from nearest drain N/A 8 If Whether road side drain exists is No - easibility to connect. Yes 9 If Whether road side drain exists is No - easibility to connect. Yes 10 Whether road side drain exists is No - Scope of widening of road N/A 11. Level of site in relation to approach road UP 12. Whether the area is subject to Low lying land 13. Whether the locality is Developing 14. Distance of the plot from the nearest temple/ monument / Airport / Other important building 1000 15. The vertical and horizontal distance from 33 KV/11 KV electric line 600 16. Whether the aplicant encroached the Govt. land/road land/any other land/rainage channel No 17. Plot size (As per measurement)(In Sqmt) 793.39 Image 18. Whether the aplicant encroached the Govt. land/road land/any other land/aring ad channel No Image 19. Sektch site plan showing the location of the site, important land marks and connectivity with the main road jat page Residential Image <	3.	Status of road	Public			
Mode of production No Whether prod side drain exists No if Whether road side drain exists is No - Distance from nearest drain N/A if Whether road side drain exists is No - easibility to connect Yes if Whether road side drain exists is No - Scope of widening of road N/A Whether the side is at road junction No Wether the side is at road junction No Wether the side is at road junction No Wether the area is subject to Low lying land Wether the locality is Developing Wether the locality is Developing The vertical and horizontal distance from 33 KV/11 KV electric line 600 Whether the aplicant encroached the Govt. land/road land/any other land/drainage channel 73.39 Whether the aplicant encroached the Govt. land/road land/any other land/drainage channel No Wether the applicant encroached the Govt. land/road land/any other land/drainage channel YES Any other information. N/A Yes Any other information. N/A Yes Land Use Residential 23.80 Kerffield the Amins report with/without site inspection and road is enclosed. (For site not located on main road) at page Yes	4.	Nature of Road	Morum			
7. if Whether road side drain exists is No - Distance from nearest drain N/A 8. if Whether road side drain exists is No - easibility to connect Yes 9. if Whether road side drain exists is No - Scope of widening of road N/A 10. Whether the site is at road junction No 11. Level of site in relation to approach road UP 12. Whether the area is subject to Low lying land 13. Whether the locality is Developing 14. Distance of the plot from the nearest temple/ monument / Airport/ Other important building 1000 15. The vertical and horizontal distance from 33 KV/11 KV electric line 600 16. Whether the aplicant encroached the Govt. land/road land/any other land/drainage channel No 19. Sketch site pian showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page YES 20. Any other information. N/A YES 21. Land Use Residential Important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page No 22. Land Use Residential Important land marks and connectivity wi	5.	Width of approach road	4.57			
nearest drainN/A8.if Whether road side drain exists is No - easibility to connectYes9.if Whether road side drain exists is No - Scope of widening of roadN/A10.Whether the site is at road junctionNo11.Level of site in relation to approach roadUP12.Whether the area is subject toLow lying land13.Whether the locality isDeveloping14.Distance of the plot from the nearest temple/ monumert / Airport/ Other important building100015.The vertical and horizontal distance from 33 KV/11 KV electric line60016.Whether the Site is vacantYes17.Plot size (As per measurement)(In Sqmt)793.3918.Whether the applicant encroached the Govt. land/road land/any other inda/drainage channelNo19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road seclosed. (For site not located on main road) at pageYES20.Any other information.N/AImage: State Sta	6.	Whether road side drain exists	No			
connectresres9.if Whether road side drain exists is No - Scope of widening of roadN/AImage: Scope of	7.		N/A			
widening of roadN/AA10.Whether the site is at road junctionNoA11.Level of site in relation to approach roadUPA12.Whether the area is subject toLow lying landA13.Whether the locality isDevelopingA14.Distance of the plot from the nearest temple/ monument / Airport/ Other important building1000A15.The vertical and horizontal distance from 33 KV/11 KV electric line600A16.Whether the Site is vacantYesA17.Plot size (As per measurement)(In Sqmt)793.39A18.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNoA19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYESA20.Any other information.N/AAA21.Verified the Amins report with/without site inspection and found correctYesA22.Land UseResidentialA23.RoadYesA24.SwerageNoA25.DrainageNoA26.Water facilityNoA27.Availability of drainNoA28.TelephoneNoA29.FacilityNoA29.FacilityNoA20.Facility of drain <td< td=""><td>8.</td><td></td><td>Yes</td><td></td><td></td></td<>	8.		Yes			
11. Level of site in relation to approach road UP 12. Whether the area is subject to Low lying land 13. Whether the locality is Developing 14. Distance of the plot from the nearest temple/ monument / Airport/ Other important building 1000 15. The vertical and horizontal distance from 33 KV/11 KV electric line 600 16. Whether the Site is vacant Yes 17. Plot size (As per measurement)(In Sqmt) 793.39 18. Whether the applicant encroached the Govt. land/road land/any other land/drainage channel No 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page YES 20. Any other information. N/A 21. Verified the Amins report with/without site inspection and found correct Yes 22. Land Use Residential 23. Road Yes 24. Sewerage No 25. Drainage No 26. Water facility No 27. Availability of drain No 28. Telephone No	9.		N/A			
22. Whether the area is subject to Low lying land 33. Whether the locality is Developing 44. Distance of the plot from the nearest temple/ monument / Airport/ Other important building 1000 15. The vertical and horizontal distance from 33 KV/11 KV electric line 600 16. Whether the Site is vacant Yes 17. Plot size (As per measurement)(In Sqmt) 793.39 18. Whether the applicant encroached the Govt. land/road land/any other land/drainage channel No 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page YES 20. Any other information. N/A 21. Verified the Amins report with/without site inspection and found correct Yes 22. Land Use Residential 23. Road Yes 24. Sewerage No 25. Drainage No 26. Water facility No 27. Availability of drain No 28. Telephone No 29. Flephone No <	10.	Whether the site is at road junction	No			
Interfact and a beta beta beta beta beta beta beta be	11.	Level of site in relation to approach road	UP			
Interface of the plot from the nearest temple/ monument / Airport/ Other important building100015.The vertical and horizontal distance from 33 KV/11 KV electric line60016.Whether the Site is vacantYes17.Plot size (As per measurement)(In Sqmt)793.3918.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNo19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYES20.Any other information.N/A21.Verified the Amins report with/without site inspection and found correctYes22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityNo27.Availability of drainNo28.TelephoneNo29.ElectricityNo	12.	Whether the area is subject to	Low lying land			
monument / Airport/ Other important building100015.The vertical and horizontal distance from 33 KV/11 KV electric line60016.Whether the Site is vacantYes17.Plot size (As per measurement)(In Sqmt)793.3918.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNo19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYES20.Any other information.N/A21.Verified the Amins report with/without site inspection and found correctResidential22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityNo27.Availability of drainNo28.TelephoneNo29.ElectricityNo	13.	Whether the locality is	Developing			
electric lineb0016.Whether the Site is vacantYes17.Plot size (As per measurement)(In Sqmt)793.3918.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNo19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at 	14.		1000			
Inducts one of the brackInductsPlot size (As per measurement)(In Sqmt)793.3918.Whether the applicant encroached the Govt. land/road land/any other land/drainage channelNo19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYES20.Any other information.N/A21.Verified the Amins report with/without site inspection and found correctYes22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityNo27.Availability of drainNo28.TelephoneNo29.ElectricityNo	15.		600			
18. Whether the applicant encroached the Govt. land/road land/any other land/drainage channel No 19. Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page YES 20. Any other information. N/A 21. Verified the Amins report with/without site inspection and found correct Yes 22. Land Use Residential 23. Road Yes 24. Sewerage No 25. Drainage No 26. Water facility No 27. Availability of drain No 28. Telephone No 29. Electricity No	16.	Whether the Site is vacant	Yes			
Iand/any other land/drainage channelNO19.Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYES20.Any other information.N/A21.Verified the Amins report with/without site inspection and found correctYes22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityNo27.Availability of drainNo28.TelephoneNo29.ElectricityNo	17.	Plot size (As per measurement)(In Sqmt)	793.39			
important land marks and connectivity with the main road is enclosed. (For site not located on main road) at pageYESImage20.Any other information.N/AImage21.Verified the Amins report with/without site inspection and found correctYesImage22.Land UseResidentialImage23.RoadYesImageImage24.SewerageNoImageImage25.DrainageNoImageImage26.Water facilityNoImageImage27.Availability of drainNoImageImage28.TelephoneNoImageImage29.ElectricityNoImageImage	18.		No			
21.Verified the Amins report with/without site inspection and found correctYesImage: Constraint of the Amins report with/without site inspection and found correct22.Land UseResidentialResidential23.RoadYesImage: Constraint of the Amins report with/without site inspectionYes24.SewerageNoImage: Constraint of the Amins report with/without site inspectionNo25.DrainageNoImage: Constraint of the Amins report with/without site inspectionNo26.Water facilityNoImage: Constraint of the Amins report with/without site inspectionNo27.Availability of drainNoImage: Constraint of the Amins report with/without site inspectionNo28.TelephoneNoImage: Constraint of the Amins report with/without site inspection site inspectionNo29.ElectricityNoImage: Constraint of the Amins report site inspection site inspect	19.	important land marks and connectivity with the main road is enclosed. (For site not located on main road) at	YES			
found correctresres22.Land UseResidential23.RoadYes24.SewerageNo25.DrainageNo26.Water facilityNo27.Availability of drainNo28.TelephoneNo29.ElectricityNo	20.	Any other information.	N/A			
23.RoadYesImage24.SewerageNoImage25.DrainageNoImage26.Water facilityNoImage27.Availability of drainNoImage28.TelephoneNoImage29.ElectricityNoImage	21.		Yes			
24.SewerageNoImage25.DrainageNoImage26.Water facilityNoImage27.Availability of drainNoImage28.TelephoneNoImage29.ElectricityNoImage	22.	Land Use	Residential			
25. DrainageNo25. DrainageNo26. Water facilityNo27. Availability of drainNo28. TelephoneNo29. ElectricityNo	23.	Road	Yes			
26.Water facilityNoImage: Constraint of the second	24.	Sewerage	No			
27. Availability of drain No 28. Telephone No 29. Electricity No	25.	Drainage	No			
28. Telephone No 29. Electricity No	26.	Water facility	No			
29. Electricity No	27.	Availability of drain	No			
	28.	Telephone	No			
30. Dealing with inflammable/chemical No	29.	Electricity	No			
	30.	Dealing with inflammable/chemical	No			

31.	Occupancy	No
32.	EAST	VACANT
33.	WEST	VACANT
34.	NORTH	VACANT
35.	SOUTH	ROAD
36.	Length of the Road(In Mtr.)	Up to 50 meter
37.	Existing Width of the Road(In Mtr.)	4.57
38.	Proposed Width of the Road as per Master Plan(In Mtr.)	0
39.	Width of the RoadWidening(In Mtr.)	0
40.	Plot area (As per deed)	793.39

Site Visit Photographs :









Recommendation : Verified & found Ok Remark : Site Inspection Done

> Utpala Sardar Junior Engg