Seraikela Nagar Panchayat

SITE VISIT REPORT

| Proposal Details | | | | | | |
|------------------|----------------------|------------------|---|--|--|--|
| Owner Name | : MANOJ KUMAR MAHALI | Site Visit Date | : 25 December, 2020 | | | |
| Applicant Name | : Sandeep Kumar Jha | File No. | : SNPC/BP/0064/W08/2020 | | | |
| Ward No. | : W08 | Case Type | : New | | | |
| Thana No. | : 301 | Plot No. | 315/A,315/C,315/D,314/A,314/B, | | | |
| Road No. / Name | : Gopebandu Chowk | Registration No. | : 314/C,314/D 314/5314/F,313/PART ,312 | | | |

| Site Visit Checklist | | | | | |
|----------------------|---|--|-----------|--------|--|
| # | Description | As On Site | Objection | Remark | |
| 1. | Whether Existing at Site | Yes | | | |
| 2. | Whether connected with an existing public road | Yes | | | |
| 3. | Status of road | Public | | | |
| 4. | Nature of Road | Blacktop | | | |
| 5. | Width of approach road | 11m | | | |
| 6. | Whether road side drain exists | No | | | |
| 7. | if Whether road side drain exists is No - Distance from nearest drain | 11m | | | |
| 8. | if Whether road side drain exists is No - easibility to connect | Yes | | | |
| 9. | if Whether road side drain exists is No - Scope of widening of road | 0.91 | | | |
| 10. | Whether the site is at road junction | No | | | |
| 11. | Level of site in relation to approach road | plain | | | |
| 12. | Whether the area is subject to | Low lying land | | | |
| 13. | Whether the locality is | Basti Area | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | 50m far from near of nagarpanchayat seraikella | | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | na | | | |
| 16. | Whether the Site is vacant | Yes | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 7324.81 | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | given | | | |
| 20. | Any other information. | na | | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | | |
| 22. | Land Use | Residential | | | |
| 23. | Road | Yes | | | |
| 24. | Sewerage | No | | | |
| 25. | Drainage | No | | | |
| 26. | Water facility | Yes | | | |
| 27. | Availability of drain | Yes | | | |
| 28. | Telephone | Yes | | | |
| 29. | Electricity | Yes | | - | |

| 30. | Dealing with inflammable/chemical | No |
|-----|--|--|
| 31. | Occupancy | No |
| 32. | EAST | road |
| 33. | WEST | road |
| 34. | NORTH | zilla parisad office |
| 35. | SOUTH | road |
| 36. | Length of the Road(In Mtr.) | Exceeding 50 meter and upto 100 meter |
| 37. | Existing Width of the Road(In Mtr.) | 11 |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 0 |
| 39. | Width of the RoadWidening(In Mtr.) | 0 |
| 40. | Plot area (As per deed) | 7324.81 |

Site Visit Photographs :









Recommendation : Verified & found Ok Remark : ok

> Vijay Kumar Rai Junior Engg