## Seraikela Nagar Panchayat

## SITE VISIT REPORT

Proposal Details					
Owner Name	: RAKESH KUMAR SAW	Site Visit Date	: 24 June, 2022		
Applicant Name	: DURGA PRASAD DUBEY	File No.	: SNPC/BP/0020/W03/2021/ALT2		
Ward No.	: W03	Case Type	: Addition Alteration		
Thana No.	: 301	Plot No.	101		
Road No. / Name	: SISHU MANDIR CLONY	Registration No.	: SNPC/ENG/0004/2017		

Site Visit Checklist					
#	Description	As On Site	Objection	Remark	
1.	Whether Existing at Site	Yes			
2.	Whether connected with an existing public road	Yes			
3.	Status of road	Public			
4.	Nature of Road	Morum			
5.	Width of approach road	3.96			
6.	Whether road side drain exists	No			
7.	if Whether road side drain exists is No - Distance from nearest drain	200m			
8.	if Whether road side drain exists is No - easibility to connect	Yes			
9.	if Whether road side drain exists is No - Scope of widening of road	na			
10.	Whether the site is at road junction	Yes			
11.	Level of site in relation to approach road	plain			
12.	Whether the area is subject to	Low lying land			
13.	Whether the locality is	Basti Area			
14.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	100m far from ssvm school of seraikella			
15.	The vertical and horizontal distance from 33 KV/11 KV electric line	100m-h			
16.	Whether the Site is vacant	No			
17.	if Whether the Site is vacant No - Stage of construction	1			
18.	if Whether the Site is vacant No - No of Storey	1			
19.	if Whether the Site is vacant No - Nature of construction	RCC			
20.	if Whether the Site is vacant No - Sketch enclosed at page	No			
21.	Plot size (As per measurement)(In Sqmt)	186.32			
22.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No			
23.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	given			
24.	Any other information.	ground floor is exsisting and first floor is proposed			
25.	Verified the Amins report with/without site inspection and found correct	Yes			
26.	Land Use	Residential			
27.	Road	Yes			
28.	Sewerage	No			

29.	Drainage	No
30.	Water facility	Yes
31.	Availability of drain	No
32.	Telephone	Yes
33.	Electricity	Yes
34.	Dealing with inflammable/chemical	No
35.	Occupancy	No
36.	EAST	plot no 101
37.	WEST	road
38.	NORTH	bishnu lohar
39.	SOUTH	road
40.	Length of the Road(In Mtr.)	Up to 50 meter
41.	Existing Width of the Road(In Mtr.)	3.96
42.	Proposed Width of the Road as per Master Plan(In Mtr.)	0
43.	Width of the RoadWidening(In Mtr.)	0
44.	Plot area (As per deed)	186.32

## Site Visit Photographs :





Recommendation : Verified & found Ok Remark : OK

> Kaushal Kishore Singh Junior Engg