Seraikela Nagar Panchayat

SITE VISIT REPORT

Proposal Details

Owner Name : BIRENDRA ORAON Site Visit Date : 25 March, 2022

Applicant Name : ANITA KUMARI File No. : SNPC/BP/0018/W06/2022

Ward No. : W06 Case Type : New Thana No. : 294 Plot No. 107

Road No. / Name : SUNDARPUR NEAR BSNL OFFICE Registration No. : SNPC/ENG/0019/2020

| Site Visit Checklist | | | | |
|----------------------|--|-------------------------|-----------|--------|
| # | Description | As On Site | Objection | Remark |
| 1. | Whether Existing at Site | Yes | | |
| 2. | Whether connected with an existing public road | Yes | | |
| 3. | Status of road | Public | | |
| 4. | Nature of Road | Blacktop | | |
| 5. | Width of approach road | 13m | | |
| 6. | Whether road side drain exists | No | | |
| 7. | if Whether road side drain exists is No - Distance from nearest drain | 100m | | |
| 8. | if Whether road side drain exists is No - easibility to connect | Yes | | |
| 9. | if Whether road side drain exists is No - Scope of widening of road | na | | |
| 10. | Whether the site is at road junction | No | | |
| 11. | Level of site in relation to approach road | 1.22m down | | |
| 12. | Whether the area is subject to | NA | | |
| 13. | Whether the locality is | Developing | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | 250m far from co office | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | 1mtr | | |
| 16. | Whether the Site is vacant | Yes | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 546.3 | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | given | | |
| 20. | Any other information. | na | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | |
| 22. | Land Use | Residential | | |
| 23. | Road | Yes | | |
| 24. | Sewerage | No | | |
| 25. | Drainage | No | | |
| 26. | Water facility | No | | |
| 27. | Availability of drain | No | | |
| 28. | Telephone | No | | |
| 29. | Electricity | No | | |
| 30. | Dealing with inflammable/chemical | No | | |

Page 1 of 3 Printed on: 29 March, 2022

| 31. | Occupancy | No |
|-----|--|---------------------------------------|
| 32. | EAST | part of plot no 106 |
| 33. | WEST | road |
| 34. | NORTH | part of plot no 106 |
| 35. | SOUTH | bishwanath murmu |
| 36. | Length of the Road(In Mtr.) | Exceeding 50 meter and upto 100 meter |
| 37. | Existing Width of the Road(In Mtr.) | 13 |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 0 |
| 39. | Width of the RoadWidening(In Mtr.) | 0 |
| 40. | Plot area (As per deed) | 546.3 |

Site Visit Photographs:







Page 2 of 3 Printed on: 29 March, 2022





Recommendation: Verified & found Ok

 $\textbf{Remark} \hspace{0.1cm} : \hspace{0.1cm} ok \hspace{0.1cm}$

Vijay Kumar Rai Junior Engg

Page 3 of 3 Printed on: 29 March, 2022