Seraikela Nagar Panchayat

SITE VISIT REPORT

Proposal Details

Owner Name : SUKDEV PARJAPATI Site Visit Date : 24 June, 2022

Applicant Name : ANITA KUMARI File No. : SNPC/BP/0032/W04/2022

Ward No. : W04 Case Type : New

Thana No. : 301 Plot No. 440/a,490/a

Road No. / Name : Registration No. : SNPC/ENG/0019/2020

| Site Visit Checklist | | | | | | | |
|----------------------|--|--|-----------|--------|--|--|--|
| # | Description | As On Site | Objection | Remark | | | |
| 1. | Whether Existing at Site | Yes | | | | | |
| 2. | Whether connected with an existing public road | Yes | | | | | |
| 3. | Status of road | Public | | | | | |
| 4. | Nature of Road | Blacktop | | | | | |
| 5. | Width of approach road | 9.5 | | | | | |
| 6. | Whether road side drain exists | Yes | | | | | |
| 7. | if Whether road side drain exists is Yes - Width | 1.07 | | | | | |
| 8. | if Whether road side drain exists is Yes - Nature | Concrete | | | | | |
| 9. | if Whether road side drain exists is Yes - Whether connected to | Public Drain | | | | | |
| 10. | Whether the site is at road junction | No | | | | | |
| 11. | Level of site in relation to approach road | plain | | | | | |
| 12. | Whether the area is subject to | Low lying land | | | | | |
| 13. | Whether the locality is | Basti Area | | | | | |
| 14. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | 200m far from birsa munda stadium seraikella | | | | | |
| 15. | The vertical and horizontal distance from 33 KV/11 KV electric line | 10m-h | | | | | |
| 16. | Whether the Site is vacant | Yes | | | | | |
| 17. | Plot size (As per measurement)(In Sqmt) | 627.1 | | | | | |
| 18. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | | | |
| 19. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | given | | | | | |
| 20. | Any other information. | during site visite some construction work has been done | | | | | |
| 21. | Verified the Amins report with/without site inspection and found correct | Yes | | | | | |
| 22. | Land Use | Residential | | | | | |
| 23. | Road | Yes | | | | | |
| 24. | Sewerage | No | | | | | |
| 25. | Drainage | Yes | | | | | |
| 26. | Water facility | Yes | | | | | |
| 27. | Availability of drain | Yes | | | | | |
| 28. | Telephone | Yes | | | | | |
| 29. | Electricity | Yes | | | | | |

Page 1 of 3 Printed on: 05 July, 2022

| 30. | Dealing with inflammable/chemical | No | |
|-----|--|---------------------------------------|--|
| 31. | Occupancy | No | |
| 32. | EAST | road | |
| 33. | WEST | plot no 470 and others | |
| 34. | NORTH | plotno 488,490 | |
| 35. | SOUTH | plot no 491 | |
| 36. | Length of the Road(In Mtr.) | Exceeding 50 meter and upto 100 meter | |
| 37. | Existing Width of the Road(In Mtr.) | 9.5 | |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 0 | |
| 39. | Width of the RoadWidening(In Mtr.) | 0 | |
| 40. | Plot area (As per deed) | 627.1 | |

Site Visit Photographs:







Page 2 of 3 Printed on: 05 July, 2022





Recommendation: Verified & found Ok

 $\textbf{Remark} \hspace{0.1cm} : \hspace{0.1cm} ok \hspace{0.1cm}$

Kaushal Kishore Singh Junior Engg

Page 3 of 3 Printed on: 05 July, 2022