Seraikela Nagar Panchayat

SITE VISIT REPORT

Proposal Details

Owner Name : St. Francis De Sales School Seraikella Site Visit Date : 27 August, 2024

Applicant Name : ABHISHEK TEWARI File No. : SNPC/BP/0035/W01/2024

Ward No.: W01Case Type: Addition AlterationThana No.: 295Plot No.288,290,291,292,293Road No. / Name: GHUTUSAI/ SFS SCHOOLRegistration No.: SNPC/ARC/0025/2021

| Site Visit Checklist | | | | | | | |
|----------------------|--|--|-----------|--------|--|--|--|
| # | Description | As On Site | Objection | Remark | | | |
| 1. | Whether Existing at Site | Yes | | | | | |
| 2. | Whether connected with an existing public road | Yes | | | | | |
| 3. | Status of road | Public | | | | | |
| 4. | Nature of Road | Blacktop | | | | | |
| 5. | Width of approach road | 9.14 | | | | | |
| 6. | Whether road side drain exists | Yes | | | | | |
| 7. | if Whether road side drain exists is Yes - Width | 1m | | | | | |
| 8. | if Whether road side drain exists is Yes - Nature | Concrete | | | | | |
| 9. | if Whether road side drain exists is Yes - Whether connected to | Public Drain | | | | | |
| 0. | Whether the site is at road junction | No | | | | | |
| .1. | Level of site in relation to approach road | Avarage plain | | | | | |
| .2. | Whether the area is subject to | NA | | | | | |
| L3. | Whether the locality is | Basti Area | | | | | |
| L4. | Distance of the plot from the nearest temple/ monument / Airport/ Other important building | SFS Schhol Campus | | | | | |
| .5. | The vertical and horizontal distance from 33 KV/11 KV electric line | 100m | | | | | |
| 6. | Whether the Site is vacant | Yes | | | | | |
| .7. | Plot size (As per measurement)(In Sqmt) | 15060.3 | | | | | |
| .8. | Whether the applicant encroached the Govt. land/road land/any other land/drainage channel | No | | | | | |
| l9. | Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page | given | | | | | |
| 20. | Any other information. | 2 building was exsisting and working site is vacant | | | | | |
| 1. | Verified the Amins report with/without site inspection and found correct | Yes | | | | | |
| 2. | Land Use | Residential | | | | | |
| 3. | Road | Yes | | | | | |
| 4. | Sewerage | No | | | | | |
| 5. | Drainage | Yes | | | | | |
| 6. | Water facility | Yes | | | | | |
| 27. | Availability of drain | Yes | | | | | |
| 28. | Telephone | Yes | | | | | |
| 9. | Electricity | Yes | | | | | |

Page 1 of 3 Printed on: 28 August, 2024

| 30. | Dealing with inflammable/chemical | No | |
|-----|--|---------------------------------------|--|
| 31. | Occupancy | No | |
| 32. | EAST | road | |
| 33. | WEST | others plot | |
| 34. | NORTH | road | |
| 35. | SOUTH | others plot | |
| 36. | Length of the Road(In Mtr.) | Exceeding 50 meter and upto 100 meter | |
| 37. | Existing Width of the Road(In Mtr.) | 9.14 | |
| 38. | Proposed Width of the Road as per Master Plan(In Mtr.) | 9.14 | |
| 39. | Width of the RoadWidening(In Mtr.) | 0 | |
| 40. | Plot area (As per deed) | 15060.3 | |

Site Visit Photographs:







Page 2 of 3 Printed on: 28 August, 2024





 $\textbf{Recommendation} \ : \ Verified \ \& \ found \ Ok$

 $\textbf{Remark} \hspace{0.1cm} : \hspace{0.1cm} ok \hspace{0.1cm}$

Ajay Sundi Junior Engg

Page 3 of 3 Printed on: 28 August, 2024