## Form IV

Certificate for Structure Stability (CSS)

(This certificate Adher is to Jhankhand Municipal Act 2011, Jhankhand Regional Development Authority Act 2002, Mineral Area Development Authority Act, & Jhankhand Building Bye Laws 2018)

: Koderma. Owner/Builder Name : Ripusudan PrandVillage Name / Mouza Name Name of Local body : Greneral : nagar Panchayat Kalesoma: Type Residential Plot No. :3716 Occupancy Type/Parpose Werd No. Supervision Certificate (SC) (No) : KONPAR/SC/03/2023 Thrus name / No. : 333 lesue date of Supervision Certificate Struct address : dud himati Kodermipplication / file no. : KOKPAR/02/2023 : near yurseas hotel Date and Time of Application / file Landmark / Locality Khusra/ Khatian No. Name of Associated Technical Person (if any) : 61

With respect to the building work for above said project/proposal type with respect of above referred plot, I certify that the structural calculations, plane and details including the relevant specifications of the building prepared by me, satisfy the structural safety requirements for all situations including natural dispeters like cyclone & certh quake etc; an applicable under the Byelaws and stipulated under Part-8 (Structural Design) of the National Building Code of India, 2005 and other relevant codes; and the information given in this is factually correct to the best of my knowledge.

I undertake the responsibility with regard to supervision of the work at each and every stage of construction of the structure, regularly to the effect that the building its being constructed conforming to the structural plan prepared structural calculations, plans and details including the relevant specifications of the building prepared by me

I will be responsible and liable for action by (Name of ULB) Govt of Jhankhand if the plant design contain misrepresentation or fraudulent information and this construction is made in deviation from structural calculations, plans and details including the relevant specifications of the building prepared by the or if there is any structural failure due wrong tunsate structural design use of low quality material and/ or poor workmanship endangering the safety of immates or public and this structural stability of the building.

Name of Structure Engineer / Civil Engineer)
Registration No. ILCANEC/SU.P/0002/2017
Validity No.18/08/28/29

Validity No. 121. US/1. 12 25 Address: NEatt. Cristle School, Koderma Authorized Signatory
(Name of Owner/Builder)

Registration No.....

Auktress:.....