Dhanbad Municipal Corporation

SITE VISIT REPORT

Proposal Details

Owner Name : SRI KRISHNA PRASAD CHOURASIA Site Visit Date : 31 October, 2017

Applicant Name : SUSHIL KUMAR File No. : DMC/BP/0106/W21/2017

 Ward No.
 : W21
 Case Type
 : New

 Thana No.
 : 06
 Plot No.
 758 , 757

Road No. / Name : Registration No. : DMC/ENG/0005/2016

Site Visit Checklist				
#	Description	As On Site	Objection	Remark
1.	Approach Road			
2.	Whether Existing at Site	Yes		
3.	Whether connected with an existing public road	Yes		
4.	Status of road	Public		
5.	Nature of Road	Kutchha		
6.	Width of approach road	6.70		
7.	Whether road side drain exists	No		
8.	if Whether road side drain exists is No - Distance from nearest drain	110		
9.	if Whether road side drain exists is No - easibility to connect	Yes		
10.	if Whether road side drain exists is No - Scope of widening of road	NO		
11.	Site Situation			
12.	Whether the site is at road junction	No		
13.	Level of site in relation to approach road	0.152		
14.	Whether the area is subject to	Affected by drainage channel		
15.	Whether the locality is	Basti Area		
16.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	380		TEMPLE
17.	The vertical and horizontal distance from 33 KV/11 KV electric line	220		11kv
18.	Site Details			
19.	Whether the Site is vacant	Yes		
20.	Plot size (As per measurement)(In Sqmt)	284.01		
21.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No		
22.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	NO		
23.	Any other information.	NO		
24.	Verification Details			
25.	Verified the Amins report with/without site inspection and found correct	No		
26.	If No, Reason	NO		
27.	Verified the cadastral map			
28.	Land Use	Residential		
29.	Existing off site Physical Infrastructure:			
30.	Road	Yes		

Page 1 of 5 Printed on: 08 November, 2017

31.	Sewerage	No
32.	Drainage	No
33.	Water facility	Yes
34.	Availability of drain	Yes
35.	Telephone	Yes
36.	Electricity	Yes
37.	Risk Parameter	
38.	Dealing with inflammable/chemical	No
39.	Occupancy	Yes
40.	Site Surrounded by (physical features)	
41.	EAST	PLOT
42.	WEST	HOUSE
43.	NORTH	PLOT
44.	SOUTH	ROAD
45.	Length of the Road(In Mtr.)	Exceeding 50 meter and upto 100 meter
46.	Existing Width of the Road(In Mtr.)	3.04
47.	Proposed Width of the Road as per Master Plan(In Mtr.)	0.01
48.	Width of the RoadWidening(In Mtr.)	1.554

Site Visit Photographs:





Page 2 of 5 Printed on: 08 November, 2017























Recommendation : Remark :

Bikash Kumar Junior Engg

Page 5 of 5 Printed on: 08 November, 2017