## **Dhanbad Municipal Corporation**

## **SITE VISIT REPORT**

**Proposal Details** 

Owner Name : SMT GITA DEVI Site Visit Date : 26 March, 2018

Applicant Name : AMARENDRA KUMAR File No. : DMC/BP/0178/W33/2017

Ward No.: W33Case Type: NewThana No.: 51Plot No.559

Road No. / Name : Registration No. : DMC/ENG/0009/2016

Site Visit Checklist						
#	Description	As On Site	Objection	Remark		
1.	Approach Road					
2.	Whether Existing at Site	Yes				
3.	Whether connected with an existing public road	Yes				
4.	Status of road	Public				
5.	Nature of Road	Concrete				
6.	Width of approach road	5.18				
7.	Whether road side drain exists	Yes				
8.	if Whether road side drain exists is Yes - Width	0.609				
9.	if Whether road side drain exists is Yes - Nature	Concrete				
10.	if Whether road side drain exists is Yes - Whether connected to	Public Drain				
11.	if Whether road side drain exists is No - Distance from nearest drain					
	if Whether road side drain exists is No - easibility to connect					
13.	if Whether road side drain exists is No - Scope of widening of road					
14.	Site Situation					
15.	Whether the site is at road junction	No				
16.	Level of site in relation to approach road	0.01				
17.	Whether the area is subject to	Affected by drainage channel				
18.	Whether the locality is	Developing				
19.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	120				
20.	The vertical and horizontal distance from 33 KV/11 KV electric line	85				
21.	Site Details					
22.	Whether the Site is vacant	Yes				
23.	if Whether the Site is vacant No - No of Storey					
24.	if Whether the Site is vacant No - Nature of construction					
25.	if Whether the Site is vacant No - Sketch enclosed at page					
26.	Plot size (As per measurement)(In Sqmt)	178.37				
27.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No				
28.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	NO				
29.	Any other information.	NO				

Page 1 of 5 Printed on: 28 March, 2018

30.	Verification Details		
31.	Verified the Amins report with/without site inspection and found correct	No	
32.	If No, Reason	NO	
33.	Verified the cadastral map		
34.	Land Use	Residential	
35.	Existing off site Physical Infrastructure:		
36.	Road	Yes	
37.	Sewerage	No	
38.	Drainage	Yes	
39.	Water facility	Yes	
40.	Availability of drain	Yes	
41.	Telephone	Yes	
42.	Electricity	Yes	
43.	Risk Parameter		
44.	Dealing with inflammable/chemical	No	
45.	Occupancy	Yes	
46.	Site Surrounded by (physical features)		
47.	EAST	APARTMENT	
48.	WEST	HOUSE	
49.	NORTH	ROAD	
50.	SOUTH	BOUNDARY WALL	
51.	Length of the Road(In Mtr.)	Exceeding 50 meter and upto 100 meter	
52.	Existing Width of the Road(In Mtr.)	5.18	
53.	Proposed Width of the Road as per Master Plan(In Mtr.)	5.18	
54.	Width of the RoadWidening(In Mtr.)	0	

## **Site Visit Photographs:**



Page 2 of 5 Printed on: 28 March, 2018























Recommendation : Remark :

Riya Patra Junior Engg

Page 5 of 5 Printed on: 28 March, 2018