## **Dhanbad Municipal Corporation**

## **SITE VISIT REPORT**

**Proposal Details** 

Owner Name : Smt. Manti Devi Site Visit Date : 30 July, 2017

Applicant Name : AMARENDRA KUMAR File No. : DMC/BP/0064/W20/2017

Ward No. : W20 Case Type : New

Thana No. : 7 Plot No. 306, 313, 314

Road No. / Name : Registration No. : DMC/ENG/0009/2016

Site Visit Checklist				
#	Description	As On Site	Objection	Remark
1.	Approach Road			
2.	Whether Existing at Site	Yes		
3.	Whether connected with an existing public road	Yes		
4.	Status of road	Public		
5.	Nature of Road	Concrete		
6.	Width of approach road	6.095		
7.	Whether road side drain exists	Yes		
8.	if Whether road side drain exists is Yes - Width	0.761		
9.	if Whether road side drain exists is Yes - Nature	Concrete		
10.	if Whether road side drain exists is Yes - Whether connected to	Public Drain		
11.	Site Situation			
12.	Whether the site is at road junction	No		
13.	Level of site in relation to approach road	0.457		
14.	Whether the area is subject to	Water logging		
15.	Whether the locality is	Developing		
16.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	350		TEMPLE
17.	The vertical and horizontal distance from 33 KV/11 KV electric line	300		11KV
18.	Site Details			
19.	Whether the Site is vacant	Yes		
20.	Plot size (As per measurement)(In Sqmt)	416.41		
21.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No		
22.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	NO		
23.	Any other information.	NO		
24.	Verification Details			
25.	Verified the Amins report with/without site inspection and found correct	No		
26.	If No, Reason	NO		
27.	Verified the cadastral map			
28.	Land Use	Residential		
29.	Existing off site Physical Infrastructure:			
30.	Road	Yes		
31.	Sewerage	No		

Page 1 of 3 Printed on: 06 September, 2017

32.	Drainage	Yes
33.	Water facility	Yes
34.	Availability of drain	Yes
35.	Telephone	Yes
36.	Electricity	Yes
37.	Risk Parameter	
38.	Dealing with inflammable/chemical	No
39.	Occupancy	Yes
40.	Site Surrounded by (physical features)	
41.	EAST	ROAD
42.	WEST	PLOT
43.	NORTH	DRAIN
44.	SOUTH	GEETA DEVI
45.	Length of the Road(In Mtr.)	Exceeding 300 meter and upto 400 meter
46.	Existing Width of the Road(In Mtr.)	3.962
47.	Proposed Width of the Road as per Master Plan(In Mtr.)	0.001
48.	Width of the RoadWidening(In Mtr.)	3.75

## Site Visit Photographs:





Page 2 of 3 Printed on: 06 September, 2017





**Recommendation**: Having Objections & require to raise shortfall

Remark :

Bikash Kumar Junior Engg

Page 3 of 3 Printed on: 06 September, 2017