## **Dhanbad Municipal Corporation**

## SITE VISIT REPORT

Prop	osal Details					
Owner Name : Mithun Dutta		Site Visit Date	: 21 November, 2017			
Applicant Name : PIYUSH KANTI SINGH		File No.	: DMC/BP/0134/W23/2017			
Ward	d No. : W23	Case Type	: New			
Thana No. : 12		Plot No.	3329 P, 3263P			
Road	d No. / Name : Near Hari Mandir 3 No. Lane Poddarpara Jharia Dhanbad	Registration No.	: DMC/ENG/0020,	/2016		
	Site Visit Checklist					
#	Description	As On Site	Objection	Remark		
1.	Approach Road					
2.	Whether Existing at Site	Yes				
3.	Whether connected with an existing public road	Yes				
4.	Status of road	Public				
5.	Nature of Road	Concrete				
6.	Width of approach road	4.11				
7.	Whether road side drain exists	Yes				
8.	if Whether road side drain exists is Yes - Width	0.166				
9.	if Whether road side drain exists is Yes - Nature	Earth				
10.	if Whether road side drain exists is Yes - Whether connected to	OutFall				
11.	Site Situation					
12.	Whether the site is at road junction	No				
13.	Level of site in relation to approach road	0.01				
14.	Whether the area is subject to	Affected by drainage channel				
15.	Whether the locality is	Developing				
16.	Distance of the plot from the nearest temple/ monument / Airport/ Other important building	480				
	The vertical and horizontal distance from 33 KV/11 KV electric line	85				
18.	Site Details					
19.	Whether the Site is vacant	Yes				
20.	Plot size (As per measurement)(In Sqmt)	200.94				
21.	Whether the applicant encroached the Govt. land/road land/any other land/drainage channel	No				
22.	Sketch site plan showing the location of the site, important land marks and connectivity with the main road is enclosed. (For site not located on main road) at page	NO				
23.	Any other information.	No				
24.	Verification Details					
	Verified the Amins report with/without site inspection and found correct	No				
26.	If No, Reason	NO				
27.	Verified the cadastral map					
28.	Land Use	Residential				
29.	Existing off site Physical Infrastructure:					
	Road	Yes				

31.	Sewerage	No
32.	Drainage	Yes
33.	Water facility	Yes
34.	Availability of drain	Yes
35.	Telephone	Yes
36.	Electricity	Yes
37.	Risk Parameter	
38.	Dealing with inflammable/chemical	No
39.	Occupancy	Yes
40.	Site Surrounded by (physical features)	
41.	EAST	PLOT
42.	WEST	HOUSE
43.	NORTH	VACANT LAND
44.	SOUTH	ROAD
45.	Length of the Road(In Mtr.)	Up to 50 meter
46.	Existing Width of the Road(In Mtr.)	4.11
47.	Proposed Width of the Road as per Master Plan(In Mtr.)	4.11
48.	Width of the RoadWidening(In Mtr.)	0.99

## Site Visit Photographs :















Recommendation : Verified & found Ok Remark : SITE VISIT DONE OK.

Bikash Kumar Junior Engg